

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

REVIEWED

By Kristen Lynch at 11:38 am, Nov 01, 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 <sup>th</sup> Street	Telephone No. 575-748-1471	
Facility Name Undaunted BSD State Com #1H	Facility Type Battery	

Surface Owner State	Mineral Owner State	API No. 30-025-40408
------------------------	------------------------	-------------------------

#### LOCATION OF RELEASE

Unit Letter O	Section 2	Township 25S	Range 32E	Feet from the 175	North/South Line South	Feet from the 2200	East/West Line East	County Lea
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.15275 Longitude 103.64421

#### NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 30 B/PW	Volume Recovered 30 B/PW
Source of Release Steel flow line	Date and Hour of Occurrence 10/16/2016; AM	Date and Hour of Discovery 10/16/2016; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kristen Lynch/NMOCD I	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 10/17/2016; 7:31 AM (Email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Steel water line going from the heater to the produced water tank failed. Vacuum truck(s) and roustabout crews were called.

Describe Area Affected and Cleanup Action Taken.\*

Approximate area: 100' X 30'. **This battery is a hard sided containment with a liner.** The steel line was repaired/replaced and all produced water was recovered. **Depth to Ground Water: >110' (approximately 215', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Based on the battery is lined and all produced water was recovered, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Robert Asher	Approved by Environmental Specialist: 		
Title: Sr. Environmental Supervisor	Approval Date: <b>11/1/2016</b>	Expiration Date: <b>N/A</b>	
E-mail Address: boba@yatespetroleum.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: October 27, 2016	Phone: 575-748-4217	<b>1RP- N/A</b>	<b>1RP 4482</b>

\* Attach Additional Sheets If Necessary

nKL1630641999  
pKL1630642157