

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

REVIEWED
By Kristen Lynch at 12:29 pm, Nov 01, 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 th Street	Telephone No. 575-748-1471	
Facility Name Farber BOB & Resolute BTO Federal Battery	Facility Type Battery	
Surface Owner Federal	Mineral Owner Federal	API No. 30-025-39525

LOCATION OF RELEASE

Unit Letter M	Section 1	Township 25S	Range 32E	Feet from the 330	North/South Line South	Feet from the 660	East/West Line West	County Lea
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.15319 Longitude 103.63496

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 40 B/PW	Volume Recovered 38 B/PW
Source of Release Knockout	Date and Hour of Occurrence 10/23/2016; PM	Date and Hour of Discovery 10/23/2016/2016; PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kristen Lynch/NMOCD I	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 10/24/2016; 1:03 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Sight glass on knockout broke, causing the release. Vacuum truck(s) and roustabout crews were called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 90'X 60'. The valves on knock out were shut, sight glass replaced, (95%) of the released produced water was recovered using a vacuum truck and remaining produced water will be allowed to dry/evaporate. **Depth to Ground Water: >100' (approximately 325', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on 95% of the produced water recovered and repairs completed, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by Environmental Specialist: 	
Title: NM Environmental Regulatory Supervisor	Approval Date: 11/1/2016	Expiration Date: N/A
E-mail Address: boba@yatespetroleum.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: October 31, 2016	1RP- N/A	1RP 4483
Phone: 575-748-4217		

* Attach Additional Sheets If Necessary

nKL1630645041
pKL1630645224