

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

REVIEWED
By Kristen Lynch at 9:48 am, Nov 16, 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

| | | |
|--|----------------------------|----------------------|
| Name of Company: Cimarex Energy | Contact: Gloria Garza | |
| Address: 600 N Marienfeld Ste 600 Midland TX | Telephone No. 432-234-3204 | |
| Facility Name: Pipeline B 6 Federal #003 | Facility Type: Battery | |
| Surface Owner: | Mineral Owner | API No. 30-025-38045 |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| F | 6 | 19S | 34E | 2310 | N | 1980 | W | LEA |

Latitude 32.6905632 Longitude -103.6016083

NATURE OF RELEASE

| | | |
|--|---|--|
| Type of Release : Produced water | Volume of Release: 120 BBLS | Volume Recovered: 120 BBLS |
| Source of Release : Produced water tank | Date and Hour of Occurrence: 11/6/2016 2:00 AM | Date and Hour of Discovery: 11/6/2016 2:00 AM |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Kristen Lynch | |
| By Whom? Gloria Garza | Date and Hour: 11/6/2016 2:52 AM | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Suspect lightning struck tank battery. Battery a total loss.

We recovered all of fluid released into lined containment. Contaminated gravel will be disposed of.

Describe Area Affected and Cleanup Action Taken.*

All fluids remained inside a lined containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|------------------------------------|--|---|
| Signature: <i>Gloria Garza</i> | OIL CONSERVATION DIVISION | |
| Printed Name: Gloria Garza | Approved by Environmental Specialist: <i>Kristen Lynch</i> | |
| Title: ESH Specialist | Approval Date: 11/16/2016 | Expiration Date: N/A |
| E-mail Address: ggarza@cimarex.com | Conditions of Approval: N/A | Attached <input type="checkbox"/> IRP 4512 |
| Date: Phone: 432-234-3204 | | |

* Attach Additional Sheets If Necessary

nKL1632135044
pKL1632135219