

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: Treasure Island Federal #001H	Facility Type: Tank Battery

Surface Owner: Federal	Mineral Owner:	API No. 30-025-41776
------------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	23	24S	32E	190	South	380	East	Lea

Latitude 32.1963959 Longitude 103.6381454

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 10 bbls	Volume Recovered: 9 bbls
Source of Release: Tank Overflow	Date and Hour of Occurrence: January 9, 2017 8:00 am	Date and Hour of Discovery: January 9, 2017 8:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

RECEIVED
By Olivia Yu at 3:29 pm, Feb 28, 2017

Describe Cause of Problem and Remedial Action Taken.*

Tanks 1 and 2 overflowed because the equalizers to tanks 3 and 4 were shut. Opened the equalizers to tanks 3 and 4.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. The containment has been cleaned.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>	OIL CONSERVATION DIVISION	
Printed Name: Rebecca Haskell	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior HSE Coordinator	Approval Date: 2/28/2017	Expiration Date: xx/xx/xxxx
E-mail Address: rhaskell@concho.com	Conditions of Approval:	
Date: January 26, 2017 Phone: 432-683-7443	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.

1RP-4566

APPROVED
By Olivia Yu at 7:23 am, Apr 10, 2017

From: Rebecca Haskell
To: Yu_Olivia_EMNRD
Cc: Oberding_Tomas_EMNRD
Subject: FW: (C-141 Final) Treasure Island Federal 1H Battery 1-9-17 (30-025-41776) 1RP-4566
Date: Friday, April 7, 2017 2:02:17 PM
Attachments: [D1 COG Treasure Island Federal 1H Battery Final C-141 1-9-17 \(30-025-41776\) 1RP-4566.pdf](#)

Ms. Yu,

As per our conversation on April 4, 2017, regarding lined facilities:

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank You,

Becky Haskell
Senior HSE Coordinator
COG Operating LLC
600 W Illinois Avenue | Midland, TX 79701
Direct: 432-818-2372 | Main: 432.683.7443
Cell: 432-556-5130
rhaskell@concho.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Yu, Olivia, EMNRD [<mailto:Olivia.Yu@state.nm.us>]
Sent: Tuesday, February 28, 2017 4:33 PM
To: Rebecca Haskell; stucker@blm.gov
Cc: Oberding, Tomas, EMNRD; Jim Amos (jamos@blm.gov)
Subject: [External] RE: (C-141 Final) Treasure Island Federal 1H Battery 1-9-17 (30-025-41776) 1RP-4566

Dear Ms. Haskell:

Please see the attachment for your records.

Please inspect the liner in question. It is OCD's understanding that all impacted material in the containment has been removed and the liner inspected for integrity. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids. Pictures and a record of the removal of contaminated fill or proper disposal of liquids are strongly encouraged to accompany submission of initial C-141s.

Thanks,

Olivia Yu
Environmental Specialist
NMOCD, District I
Olivia.yu@state.nm.us
575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Rebecca Haskell [<mailto:RHaskell@concho.com>]
Sent: Thursday, January 26, 2017 8:21 AM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; Lynch, Kristen, EMNRD <Kristen.Lynch@state.nm.us>; stucker@blm.gov
Cc: Oberding, Tomas, EMNRD <Tomas.Oberding@state.nm.us>; Jim Amos (jamos@blm.gov) <jamos@blm.gov>
Subject: (C-141 Final) Treasure Island Federal 1H Battery 1-9-17 (30-025-41776) 1RP-4566

Ms. Yu / Ms. Tucker,

Attached is a Final C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank You,

Becky Haskell
Senior HSE Coordinator
COG Operating LLC
600 W Illinois Avenue | Midland, TX 79701
Direct: 432-818-2372 | Main: 432.683.7443
Cell: 432-556-5130
rhaskell@concho.com



From: Yu, Olivia, EMNRD [<mailto:Olivia.Yu@state.nm.us>]
Sent: Wednesday, January 18, 2017 10:58 AM
To: Rebecca Haskell; Lynch, Kristen, EMNRD; stucker@blm.gov
Cc: Oberding, Tomas, EMNRD; Jim Amos (jamos@blm.gov)
Subject: [External] RE: (C-141 Initial) Treasure Island Federal 1H Battery 1-9-17 (30-025-41776)

**** External email. Use caution. ****

Dear Rebecca:

The RP for this incident is

4566	2017-01-18	A	COG	Treasure Island Federal 01H Battery	30-025-41776	24S-32E-23P	01/09/2017
-------------	------------	---	-----	-------------------------------------	--------------	-------------	------------

Please note that a release characterization/delineation workplan as detailed in the attachment must be approved by OCD BEFORE any remediation work.

Thanks,

Olivia Yu
Environmental Specialist; District 1
OCD-EMNRD
575-393-6161 x 113
Olivia.yu@state.nm.us

From: Rebecca Haskell [<mailto:RHaskell@concho.com>]
Sent: Wednesday, January 11, 2017 8:19 AM
To: Lynch, Kristen, EMNRD <Kristen.Lynch@state.nm.us>; stucker@blm.gov
Cc: Boarding, Tomas, EMNRD <Tomas.Oberding@state.nm.us>; Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; Jim Amos (jamos@blm.gov) <jamos@blm.gov>
Subject: (C-141 Initial) Treasure Island Federal 1H Battery 1-9-17 (30-025-41776)

Ms. Lynch/Ms. Tucker,

Attached is a C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank You,

Becky Haskell
Senior HSE Coordinator
COG Operating LLC
600 W Illinois Avenue | Midland, TX 79701
Direct: 432-818-2372 | Main: 432.683.7443
Cell: 432-556-5130
rhaskell@concho.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.