

From: [Yu, Olivia, EMNRD](#)
To: ["Mark Larson"](#)
Cc: ["Woodell, Rebecca F."](#); ["Wrangham, Calvin W."](#)
Subject: RE: 1RP-4532, Targa Eunice South Justice 4" Down Leg Delineation Report
Date: Wednesday, May 3, 2017 10:56:00 AM
Attachments: [ApprovedClosure_3May2017_1RP-4532 Addendum Delineation Report Eunice South Justice 4" Down Leg.pdf](#)

Dear Mr. Larson:

Please see attachment.

The available information indicates **OPERATOR** has met the requirements of 19.15.29 NMAC and no further corrective action is required. NMOCD considers **1RP-4532** closed. This determination by the Oil Conservation Division does not relieve Operator of responsibility should future information indicate a threat to ground water, surface water, human health, or the environment. Furthermore, it does not relieve Operator of responsibility for compliance with any federal, state, or local laws and/or regulations.

Olivia Yu
Environmental Specialist
NMOCD, District I
Olivia.yu@state.nm.us
575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Mark Larson [mailto:Mark@laenvironmental.com]
Sent: Thursday, April 13, 2017 12:57 PM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>
Cc: 'Woodell, Rebecca F.' <RebeccaWoodell@targaresources.com>; 'Wrangham, Calvin W.' <CalvinWrangham@targaresources.com>
Subject: RE: 1RP-4532, Targa Eunice South Justice 4" Down Leg Delineation Report

Dear Ms. Yu,

Please find the addendum delineation report attached for the release from the Eunice South Justice 4" down leg. The report is submitted to the New Mexico Oil Conservation Division (OCD) on behalf of Targa Midstream Services, LLC (Targa) and presents the laboratory analysis of confirmation soil samples collected from the overspray area, as requested by OCD. Please contact Cal Wrangham with Targa at (4320 688-0542 or CalvinWrangham@targaresources.com or me if you have questions.

Respectfully,

Mark Larson

From: Yu, Olivia, EMNRD [<mailto:Olivia.Yu@state.nm.us>]
Sent: Friday, March 17, 2017 1:24 PM
To: Mark Larson
Cc: 'Wrangham, Calvin W.'; 'Woodell, Rebecca F.'; Oberding, Tomas, EMNRD
Subject: RE: 1RP-4532, Targa Eunice South Justice 4" Down Leg Delineation Report

Dear Mr. Larson:

Due to the fact that the conditions of approval attached to the reviewed initial C-141 were not complied with and that depth to groundwater is at 68 ft., NMOCD requests that for confirmation

1. 4 soil samples, in the 4 cardinal directions, be collected in the overspray area at a depth of 2 ft;
2. a 6" depth background sample north of the release location on the pasture.

Laboratory analyses for Benzene, BTEX, TPH, and chlorides are required. Please confirm.

Thanks,
Olivia

From: Mark Larson [<mailto:Mark@laenvironmental.com>]
Sent: Friday, March 17, 2017 6:59 AM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>
Cc: 'Wrangham, Calvin W.' <CalvinWrangham@targaresources.com>; 'Woodell, Rebecca F.' <RebeccaWoodell@targaresources.com>
Subject: RE: 1RP-4532, Targa Eunice South Justice 4" Down Leg Delineation Report

Olivia,

Thank you for meeting with me yesterday to discuss the delineation and remediation for 1RP-4532. The surface ownership is private (Legacy). Please find the final C-141 attached. Please contact Cal Wrangham with Targa Resources at (432) 688-0542 or CalvinWrangham@targaresources.com or me if you have questions.

Respectfully,

Mark J. Larson, P.G.
President/Sr. Project Manager
507 N. Marienfeld St., Suite 205
Midland, Texas 79701
Office – 432-687-0901
Cell – 432- 556-8656
Fax – 432-687-0456
mark@laenvironmental.com