

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	BEBIDAS STATE #002H	Facility Type:	Tank Battery

Surface Owner:	State	Mineral Owner:	API No.	30-25-40855
----------------	-------	----------------	---------	-------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	16	23S	33E	392'	South	1887'	West	Lea

Latitude 32.2985573 Longitude 103.5797043

**NATURE OF RELEASE**

Type of Release:	Oil	Volume of Release:	50bbls	Volume Recovered:	49bbls
Source of Release:	Valve	Date and Hour of Occurrence:	09-21-2016 10:00am	Date and Hour of Discovery:	09-21-2016 10:00am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required				
By Whom?	Date and Hour:				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
If YES, Volume Impacting the Watercourse.					

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Valve placed in the wrong position. Place the valve in the correct position.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred within a lined facility. Vacuum trucks were dispatched to remove all freestanding fluids Concho had the free fluids and any contaminated material inside the lined facility removed. The liner has been cleaned and returned back to normal operations.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:				<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Robert Grubbs Jr.			Approved by Environmental Specialist: 	
Title:	Senior HSE Coordinator			Approval Date:	2/28/2017
E-mail Address:	rgrubbs@concho.com			Expiration Date:	
Date:	January 19, 2017	Phone:	432-683-7443	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

Please inspect liner in question.  
Provide NMOCD with a concise  
report of the inspection with  
affirmation the liner has and will  
continue to contain liquids.

pKL1627236284

1RP-4458

**APPROVED**

By Olivia Yu at 4:04 pm, Jun 08, 2017



A photograph of an industrial site. In the background is a large, green, cylindrical storage tank. In the foreground, there is a black-lined containment area, possibly for oil or chemicals. A sign is posted in the foreground, providing site information. The ground is sandy and there are some small plants. A rusty metal pole is visible on the right side of the frame.

CONCHO COG Operating LLC  
BEBIDAS STATE #2H  
UL N SEC.16-T23S-R33E  
392'FSL & 1887'FWL  
LEA COUNTY, NM  
API #30-025-40855

**From:** Rebecca Haskell  
**To:** [Yu, Olivia, EMNRD](mailto:Yu.Olivia@state.nm.us); [Amber Groves \(agroves@SLO.state.nm.us\)](mailto:agroves@SLO.state.nm.us)  
**Cc:** [Oberding, Tomas, EMNRD](#); [Rebecca Haskell](#); [Dakota Neel](#)  
**Subject:** FW: (C-141 Final) BEBIDAS STATE #002H (TB) (30-025-40855)  
**Date:** Tuesday, June 6, 2017 3:28:51 PM  
**Attachments:** [D1\\_COG\\_Bebidas State 002H \(TB\) Final.pdf](#)

---

Ms. Yu,

As per our conversation on April 4, 2017, regarding lined facilities:

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOC approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank You,

Becky Haskell  
Senior HSE Coordinator  
COG Operating LLC  
600 W Illinois Avenue | Midland, TX 79701  
Direct: 432-818-2372 | Main: 432.683.7443  
Cell: 432-556-5130  
[rhaskell@concho.com](mailto:rhaskell@concho.com)



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

---

**From:** Yu, Olivia, EMNRD [<mailto:Olivia.Yu@state.nm.us>]



**Sent:** Tuesday, February 28, 2017 3:57 PM

**To:** Robert Grubbs; Oberding, Tomas, EMNRD; 'agroves@slo.state.nm.us'

**Subject:** [External] RE: (C-141 Final) BEBIDAS STATE #002H (TB) (30-025-40855)

\*\*\*\* External email. Use caution. \*\*\*\*

Dear Mr. Grubbs:

Please see the attachment for your records.

Please inspect the liner in question. It is OCD's understanding that all impacted material in the containment has been removed and the liner inspected for integrity. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids. Pictures and a record of the removal of contaminated fill or proper disposal of liquids are strongly encouraged to accompany submission of initial C-141s.

Thanks,

Olivia Yu

Environmental Specialist

NMOCD, District I

[Olivia.yu@state.nm.us](mailto:Olivia.yu@state.nm.us)

575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

---

**From:** Robert Grubbs [<mailto:RGrubbs@concho.com>]

**Sent:** Monday, January 30, 2017 8:37 AM

**To:** Yu, Olivia, EMNRD <[Olivia.Yu@state.nm.us](mailto:Olivia.Yu@state.nm.us)>; Oberding, Tomas, EMNRD

<[Tomas.Oberding@state.nm.us](mailto:Tomas.Oberding@state.nm.us)>; 'agroves@slo.state.nm.us' <[agroves@slo.state.nm.us](mailto:agroves@slo.state.nm.us)>

**Subject:** (C-141 Final) BEBIDAS STATE #002H (TB) (30-025-40855)

Ms. YU / Ms. GROVES,

ATTACHED IS A C-141 FOR YOUR CONSIDERATION. IF YOU HAVE ANY ADDITIONAL QUESTIONS PLEASE FEEL FREE TO CONTACT ME.

THANK YOU,

ROBERT GRUBBS JR.  
SR. HSE. COORDINATOR  
432.683.7443 (MAIN)  
432.818.2369 (DIRECT)  
432.661.6601 (CELL)  
432.221.0892 (FAX)  
[RGRUBBS@CONCHO.COM](mailto:RGRUBBS@CONCHO.COM)  
MAILING ADDRESS:  
ONE CONCHO CENTER  
600 W. ILLINOIS AVENUE  
MIDLAND, TEXAS 79701

CONFIDENTIALITY NOTICE: THE INFORMATION IN THIS EMAIL MAY BE CONFIDENTIAL AND/OR PRIVILEGED. IF YOU ARE NOT THE INTENDED RECIPIENT OR AN AUTHORIZED REPRESENTATIVE OF THE INTENDED RECIPIENT, YOU ARE HEREBY NOTIFIED THAT ANY REVIEW, DISSEMINATION OR COPYING OF THIS EMAIL AND ITS ATTACHMENTS, IF ANY, OR THE INFORMATION HEREIN, IS PROHIBITED. IF YOU RECEIVED THIS EMAIL IN ERROR, PLEASE IMMEDIATELY NOTIFY THE SENDER BY RETURN EMAIL AND DELETE THIS EMAIL FROM YOUR SYSTEM. THANK YOU.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Further, any contract terms proposed or purportedly accepted in this email are not binding and are subject to management's final approval as memorialized in a separate written instrument, excluding electronic correspondence, executed by an authorized representative of COG Operating LLC or its affiliates.