

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC OGRID #229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: Macho State #002H	Facility Type: Tank Battery

Surface Owner: State	Mineral Owner: State	API No. 30-025-39885
----------------------	----------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter E	Section 02	Township 24S	Range 33E	Feet from the 2260	North/South Line North	Feet from the 330	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.2476959 Longitude -103.55056

**NATURE OF RELEASE**

Type of Release: Oil (Fire) and Produced Water	Volume of Release: EST. 0.5 bbls Oil & 0.5 bbls PW	Volume Recovered: 0 bbls
Source of Release: Flare	Date and Hour of Occurrence: June 11, 2017 8:00 am	Date and Hour of Discovery: June 11, 2017 8:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Yu NMOCD / Ms. Groves SLO	
By Whom? Rebecca Haskell	Date and Hour: June 12, 2017 Time of this email	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**

By Olivia Yu at 12:28 pm, Jun 12, 2017

Describe Cause of Problem and Remedial Action Taken.\*

This release was caused by fluid going through the flare causing a fire. The flow of fluid to the flare was shut off and the fire quickly extinguished itself.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred on location with a light mist in the pasture. No fluid was recovered due to the fire burning off any standing fluid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Rebecca Haskell	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior HSE Coordinator	Approval Date: 6/12/2017	Expiration Date:
E-mail Address: rhaskell@concho.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: June 12, 2017 Phone: 432-683-7443	NMOCD requests confirmatory laboratory analyses of discrete soil samples from impacted pasture area.	

\* Attach Additional Sheets If Necessary

nOY1716342941

1RP-4720

pOY1716343921