

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Conoco Phillips	Contact	Robert Bourque	x
Address	3300 North A Street Midland TX	Telephone No.	337-962-8672	
Facility Name	Ruby Federal	Facility Type	Production Site	

Surface Owner	BLM	Mineral Owner	BLM	API No.	30025
---------------	-----	---------------	-----	---------	-------

LOCATION OF RELEASE

30-025-70894

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	18	175	32E	2310	SouthLine	910	Eastline	Lea

Latitude 32.504118 N Longitude 103.80 W NAD83

32.83

NATURE OF RELEASE

Type of Release	Spill	Volume of Release	20 bbl	Volume Recovered	19 bbl
Source of Release	Pump Truck	Date and Hour of Occurrence		Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Pat Mckblvey BLM/ Max Brown OCD		
By Whom?		Date and Hour	7-5-17 7:30 Pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Olivia Yu at 2:38 pm, Jul 10, 2017

Describe Cause of Problem and Remedial Action Taken.*

Third party company clean thier cement tubs onto loaction after leaving the site we were drilling on. Once the spill was discovered we reported it to the BLM and awaited direction and permistion to begin cleanup.

Describe Area Affected and Cleanup Action Taken.*

The site had a 25 by 100 ft area afected by the spill and a trail approx 1 foot wide leading off location approx 190 foot long leading into were it puddled in a 10 by 27 foot spot. The spill was cleaned by EES . They scraped the affected soil up and took soil samples to be test to ensure a proper clean had taken place

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:			
Printed Name:	Robert Bourque	Approved by Environmental Specialist:	
Title:	Well Site Safety Rep	Approval Date:	7/10/2017
E-mail Address:	Robert.bourque@contractor.com	Expiration Date:	
Date:	7-10-17	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Phone:	337-962-8672		

* Attach Additional Sheets If Necessary

Provide MSDS of the
chemical(s) in the release.
Scaled map with soil sample
locations.

nOY1719153910

pOY1719154347

1RP-4753

fOY1719153561