

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Plains Pipeline, LP	Contact	Camille Bryant
Address	577 US Hwy 385 N, Seminole, TX	Telephone No.	(575) 441-1099
Facility Name	Cotton Draw Station	Facility Type	Pipeline
Surface Owner	BLM	Mineral Owner	
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	3	26S	32E					Lea

Latitude N 32.07570° Longitude W 103.67049°



NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	190 bbls	Volume Recovered	100 bbls
Source of Release	Pipeline	Date and Hour of Occurrence	04/19/2016 @ 08:40	Date and Hour of Discovery	4/19/2016 @ 08:40
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Verbal notification to Jamie Keyes		
By Whom?	Camille Bryant	Date and Hour	04/19/2016 @ 10:34		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*	<div>APPROVED By Olivia Yu at 10:21 am, Aug 10, 2017</div>				

Describe Cause of Problem and Remedial Action Taken.* Failure to recognize hazard of the removal of a blind from an active system with no use of lock-out-tag-out and failure to identify the need for coordination on simultaneous tasks on the same equipment resulted in a release of crude oil.

Describe Area Affected and Cleanup Action Taken.* The released crude oil impacted an area of approximately 53,000 square feet inside the facility, the released fluid, then flowed south and impacted an area of approximately 2,800 square feet along the outside of the fence line. The released fluid continued south impacting an area of approximately 450 square feet off the caliche pad. The impacted area was remediated and sampled as per applicable NMOCD and BLM guidelines. Please reference the "Remediation Summary and Site Closure Request" dated May 2017 for remediation details.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Camille Bryant	Approved by Environmental Specialist: 	
Title: Remediation Coordinator	Approval Date: 8/10/2017	Expiration Date: xx/xx/xxxx
E-mail Address: cjbryant@paalp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: June 23, 2017	Phone: (575) 441-1099	

* Attach Additional Sheets If Necessary

1RP-4276