

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action **Initial only**

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC OGRID # 229137	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: Tyrell Fee #001H	Facility Type: Tank Battery	
Surface Owner: Private	Mineral Owner:	API No. 30-025-41026

LOCATION OF RELEASE

Unit Letter A	Section 14	Township 24S	Range 33E	Feet from the 190	North/South Line North	Feet from the 660	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.2243729 Longitude -103.5367126

NATURE OF RELEASE

Type of Release: Oil (Fire)	Volume of Release: Est. 0.75 bbl.	Volume Recovered: 0 bbl.
Source of Release: Flare	Date and Hour of Occurrence: August 10, 2017 5:00 pm	Date and Hour of Discovery: August 10, 2017 5:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Weaver - NMOCD / Ms. Tucker - BLM	
By Whom? Rebecca Haskell	Date and Hour: August 11, 2017 Time of this Email	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

RECEIVED

By Olivia Yu at 3:11 pm, Aug 11, 2017

Describe Cause of Problem and Remedial Action Taken.*

The release was due to a vessel upset resulting in oil being sent to the flare. The back pressure valve will be replaced.

Describe Area Affected and Cleanup Action Taken.*

The fire impacted the location and an area in the pasture adjacent to the pad. No fluids were recovered due to the fire burning off any standing fluid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>	OIL CONSERVATION DIVISION	
Printed Name: Rebecca Haskell	Approved by Environmental Specialist: <i>ly</i>	
Title: Senior HSE Coordinator	Approval Date: 8/11/2017	Expiration Date:
E-mail Address: rhaskell@concho.com	Conditions of Approval: Confirmatory laboratory analyses of 1-2 discrete soil samples (0-6" bgs) from the impacted pasture area.	Attached <input type="checkbox"/>
Date: August 11, 2017 Phone: 432-683-7443		

* Attach Additional Sheets If Necessary

1RP-4788

nOY1722354800

pOY1722354974