Yvonne and Hack:

As per our meeting this morning at 9 am MST, NMOCD will consider delineation to be complete for 1RP-4736. Please see the attachment for your records. For the remediation/closure report, please submit in one aggregated pdf:

- 1. a short summary of delineation and remediation activities
- 2. documentation of depth to groundwater
- 3. photo documentation of the release site pre- and post-excavation
- 4. laboratory analyses (TPH extended and chloride) of confirmation samples for the North and South sidewalls and bottom of excavation
- 5. Scaled map with the locations of confirmation samples and release point, and notation of the depth of excavation.

Please inform if there are missing information or clarification is needed.

Thanks, Olivia

Olivia

From: Blair, Yvonne B [mailto:YBBlair@dcpmidstream.com]
Sent: Thursday, August 31, 2017 12:48 PM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>
Cc: Conder, Haskell P <HConder@dcpmidstream.com>
Subject: J-2-4-11 Line leak 1 RP-4736

## Olivia

Attached is the delineation plat and associated labs on the J-2-4-11 Line leak 1 RP-4736. After your review and based off this data we are asking for permission to backfill. I will be sending separate emails for each RP.

Yvonne Blair Compliance Coordinator DCP Midstream 575-361-2406