From: Yu, Olivia, EMNRD
To: "Chase Settle"

Cc:Katie Parker; Billings, Bradford, EMNRDSubject:RE: Vespa BME Federal #1H- 1RP-4475Date:Friday, September 22, 2017 2:54:00 PM

Attachments: image001.png

Dear Mr. Settle:

As indicated by Dr. Oberding in an email dated February 8, 2017, remedial activities completed without an approved corrective action plan will be considered completed at risk. However, NMOCD will consider delineation completed for 1RP-4475, based on the data submitted along with the unapproved Final C-141.

In order to verify remediation was completed, NMOCD requires the following items before approval for backfilling is granted.

- 1. laboratory analyses (BTEX, TPH extended, and chlorides) from a minimum of 4 sidewalls and 1 bottom samples. Please mark confirmation sample locations on a scaled map.
- 2. a statement affirming that the liner under the battery has and will continue to contain liquids. Photo documentation are required to serve as a record of the removal of contaminated fill or proper disposal of liquids.

Thanks,

Olivia Yu Environmental Specialist NMOCD, District I Olivia.yu@state.nm.us 575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Chase Settle [mailto:Chase Settle@eogresources.com]

Sent: Tuesday, September 5, 2017 1:20 PMTo: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>Cc: Katie Parker <Katie_Parker@eogresources.com>

Subject: Vespa BME Federal #1H- 1RP-4475

Ms. Yu,

I would like to know the status of this release listed below so that we can forward with backfilling the

open excavation where the initial excavation activities were completed.

Vespa BME Federal #1H 30-005-29095 Section 12, T15S-R31E 2500' FSL & 200' FEL Chaves County, New Mexico 1RP-4475

Thank you,

Chase Settle, M.S.

Rep Safety & Environmental II

EOG Resources

105 S. 4th Street Artesia, NM 88210 575-748-4171 (Office) 575-703-6537 (Cell)

