

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas	
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905	
Facility Name: Merit 32 DM St. com #1H	Facility Type: Producing Oil Well	
Surface Owner: State	Mineral Owner:	API No. 30-025-40836

### LOCATION OF RELEASE

Unit Letter D	Section 32	Township 18S	Range 35E	Feet from the 245'	North/South Line North	Feet from the 330'	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.7105675 Longitude -103.487175

### NATURE OF RELEASE

Type of Release: Oil/produced water	Volume of Release: estimated 130 bbls	Volume Recovered: 10 bbls oil/ 120 bbls pw
Source of Release: Tank Battery	Date and Hour of Occurrence 6-9-17 5:00 am	Date and Hour of Discovery 6-9-17 5:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mark Whitaker; NMOCD	
By Whom? Zack Thomas	Date and Hour 6-9-17 12:40 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**APPROVED**

**By Olivia Yu at 2:42 pm, Oct 31, 2017**


Describe Cause of Problem and Remedial Action Taken.\*

Lightning struck tank battery causing fire. Well was shut-in and all separation equipment isolated. Monument and Hobbs Fire Departments were dispatched to put out fire.

Describe Area Affected and Cleanup Action Taken.\*

Affected area- Pad surface Northwest of tank containment. Vacuum truck used to recover all standing fluid. For complete details of remediation reference the Remediation Summary submitted on October 24, 2017. Final remediation was conducted in accordance with the NMOCD's Guidelines for Remediation of Spills, Leaks and Releases.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Zack Thomas	Approved by Environmental Specialist: 	
Title: Environmental Rep.	Approval Date: 10/31/2017	Expiration Date: xx/xx/xxxx
E-mail Address: zthomas@mewbourne.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10-17-17	Phone: 575-602-2188	

\* Attach Additional Sheets If Necessary

1RP-4724