

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88212  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised April 3, 2017

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company <i>Forty Acres Energy</i>	Contact <i>Garret Johnson</i>	
Address <i>11777 Katy Frwy, Ste 305 B</i>	Telephone No. <i>832-706-6056</i>	
Facility Name <i>Lea 407 #1</i>	Facility Type <i>Battery</i>	
Surface Owner	Mineral Owner	API No.

LOCATION OF RELEASE

Unit Letter <i>K</i>	Section <i>2</i>	Township <i>21S</i>	Range <i>35E</i>	Feet from the <i>1980</i>	North/South Line <i>S</i>	Feet from the <i>1980</i>	East/West Line <i>W</i>	County <i>LEA</i>
-------------------------	---------------------	------------------------	---------------------	------------------------------	------------------------------	------------------------------	----------------------------	----------------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_ NAD83

NATURE OF RELEASE

Type of Release <i>Tank Battery</i>	Volume of Release <i>N/A</i>	Volume Recovered <i>N/A</i>
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

*No. Samples were collected down to a depth of 12' - no signs of contamination was found at this depth.*

Describe Cause of Problem and Remedial Action Taken.\*

*It became clear that this location had experienced a past release. While clearing the location, soils were excavated to the point of a contamination no longer existing. Fresh soils were used as replacement.*

Describe Area Affected and Cleanup Action Taken.\*

*The area required approx. 800 cubic yards of soil to be removed and replaced w/ fresh soil. Original contour was restored.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>D. John</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Garret Johnson</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: <i>Engineer</i>	Approval Date: <i>12/12/2017</i>	Expiration Date: <i>xx/xx/xxxx</i>
E-mail Address: <i>garret@faenergyus.com</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>12-8-17</i> Phone: <i>832-706-0056</i>		

\* Attach Additional Sheets If Necessary

1RP-4717

APPROVED

By Olivia Yu at 6:54 am, Dec 12, 2017