## State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised April 3, 2017

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19,15.29 NMAC.

220 S. St. Fran	cis Dr., Santa	a Fe, NM 87505	i	Sa	inta Fe	, NM 875	05							
			Rele	ease Notific	ation	and Co	rrective A	ction			-			
	_					<b>OPERA</b>	OR		Initia	l Report	$\boxtimes$	Final	Report	
		TC Field Ser			Contact: Rose Slade									
				Antonio, Tx 78	249 ]	Telephone No. 210-403-6525								
Facility Name: a-14 (Field Scrubber)						Facility Type: Compressor Station								
Surface Owner: BLM Mineral Owner:						N/A			API No.: N/A					
				LOCA	TION	OF REI	EASE							
Unit Letter	Section Townshi		Range	Feet from the		South Line	Feet from the	East/W	est Line		County			
I	6	248	35E			ooun Dine				Lea				
			L	atitude: <u>32.246</u>	<u>183</u> L	ongitude: -	103.40200 NAI	D83						
				NAT	TIRE	OF RELI	TASE							
Type of Rele	ase: Crude	Oil/Produced	Water		UNE	E OF RELEASE Volume of Release: <5 barrels Volume Recovered: 0								
Source of Re					Date and Hour of Occurrence:			Date and Hour of Discovery:						
						Unknown 2/23/17				-				
Was Immedia	ate Notice (		No 🗖 Not R	equired	If YES, To Whom? d Notification was given to Ms. Olivia Yu on 3/3/17 at approximately 8:19 AM.									
By Whom?						Date and Hour								
Was a Water	course Rea	ched?			If YES, Volume Impacting the Watercourse.									
			Yes 🗵	No			in the second		····					
If a Watercou	urse was Im	pacted, Descr	ibe Fully.	*						OBR	5 00	CD		
N/A		•	·	APPRO	D									
				By Olivi	a Yu	at 2:15	<b>pm, Dec</b> 1	19, 20	17	OCT 1	9 2017		:	
Describe Cau	use of Probl	em and Reme	dial Actio	n Taken.*		RECEIVED								
On 2/23/17. 1	ETC person	nel discovere	d a crude o	oil & produced wa	ater relea	se from the f	ield scrubher due	to a piec					the	
	On 2/23/17, ETC personnel discovered a crude oil & produced water release from the field scrubber due to a piece of tubing breaking off going into the field scrubber. During the initial response activities, ETC installed a new piece of tubing going into the field scrubber to prevent another incident.													
Describe Are	a Affected	and Cleanup /	Action Tal	ken.*										
		-												
				west corner of the										
District Offic	reard the P	personnel and Sureau of Land	i an envire Manager	nmental company	y represe	nting ETC. A	work-plan was v egards to the clea	written ai	nd submitte	ed to the NI the $A_1/1/C$	MOCD I	Hobbs	i	
District Office and the Bureau of Land Management (BLM). For more information in regards to the cleanup action taken at the A-14 Compressor Station Field Scrubber Release Site (1RP-4634), please reference the "Remediation Summary and Site Closure Request".														
						·								
I hereby certi	ify that the	information a	iven abov	e is true and comp	lete to th	e hest of my	knowledge and u	ndercton	d that nure	uant to NM	000 -	lec an		
regulations a	Il operators	are required t	o report a	nd/or file certain r	elease no	otifications a	id perform correct	ctive action	ons for rele	eases which	may en	dange	iu r	
public health	or the envi	ironment. The	acceptan	ce of a C-141 repo	ort by the	NMOCD m	arked as "Final R	eport" de	oes not reli	eve the ope	rator of	liabili	ity	
				investigate and r										
		addition, NMC ws and/or regi		otance of a C-141	report do	bes not reliev	e the operator of	responsil	oility for co	ompliance v	vith any	other		
(	, on jocar na	ins und of regi	$\Lambda$				OIL CON	SERV	ATION	DIVISIO	)N			
~ (	the	141	J		OIL CONSERVATION DIVISION									
Signature:		X U V	Rhi	M		by an and the second seco								
Printed Name	e: Rose L. S	Slade			4	Approved by Environmental Specialist:								
Title Sr. P.		Cmarl-1/-+					12/19/20	17	U	xx/x	x/xxx	x		
Title: Sr. Env	vironmental	specialist				Approval Da	e:	] E	xpiration	Date:		-		
E-mail Addr	ess: Rose.S	lade@energyt	ransfer.co	m	(	Conditions of	Approval:			Attached				
Date: 0-19-14 Phone: 210-403-6525														