

**REVISED**

10:09 am, Feb 09, 2018

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**  Initial Report  Final Report

Name of Company Tandem Energy Corporation	Contact Ernie Sanchez
Address 2700 Post Oak Blvd. Ste 1000 Houston, Tx 77056	Telephone No. 575-703-6865
Facility Name Yates Tank Battery	Facility Type Tank Battery

Surface Owner State	Mineral Owner State	API No. HOBS OCD
---------------------	---------------------	------------------

**LOCATION OF RELEASE**

Unit Letter O	Section 29	Township 21S	Range 35E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
---------------	------------	--------------	-----------	---------------	------------------	---------------	----------------	------------

Latitude 32.442844 N Longitude 103.386078

JUL 27 2015

RECEIVED

**NATURE OF RELEASE**

Type of Release Crude Oil	Volume of Release 40 bbls.	Volume Recovered none
Source of Release tank	Date and Hour of Occurrence	Date and Hour of Discovery 6/25/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**  
By OCD District 1 at 8:29 am, Jul 28, 2015

Describe Cause of Problem and Remedial Action Taken.\*

Dump valve on separator malfunctioned causing crude oil to be sent to water tank.

Describe Area Affected and Cleanup Action Taken.\*

Crude oil was spilled within tank area. The area of the spill will be remediated by removing all of the contaminated soil will be removed and properly disposed of.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Kimmy Watson	Approved by Environmental Specialist:	
Title: Manager, HSE and Compliance	Approval Date: 07/28/2015	Expiration Date: 09/28/2015
E-mail Address: kimmyw@t5energy.com	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guides. Geotagged photos of remediation required.	Attached <input type="checkbox"/> IRP 3768
Date: 7/1/2015 Phone: 713-987-7320		

\* Attach Additional Sheets If Necessary

pJXK1520930467

nJXK1520930187