



A photograph showing three construction workers in a large, deep excavation pit. The workers are wearing hard hats and work clothes. One worker on the left is using a shovel to move reddish-brown soil. Two other workers on the right are also working with the soil. The pit is surrounded by a red safety fence. In the background, there are some construction materials and equipment.

Merryman Const Co.
Backfilled West Sump @
Jal #3 plant. Liner was
added to top of fiberglass
tank. Remaining shown
backfilled with top soils



WESTER
BOILER
SUMP
BURIED
BELOW