

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Stakeholder Midstream, LLC	Contact: Rory Gray	
Address: 401 E. Sonterra Blvd. Ste. 215, San Antonio, Texas	Telephone No. 210-444-9664	
Facility Name: Crude Pipeline	Facility Type: Crude Pipeline	
Surface Owner: James W. Spears	Mineral Owner	API No. Operator No. 371407

LOCATION OF RELEASE

Unit Letter	Section 10	Township 14S	Range 38E	Feet from the	North/South Line	Feet from the	East/West Line	County
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	--------

Latitude 33.111856 Longitude -103.080665 NAD83

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 15	Volume Recovered: 12
Source of Release: Line strike on pipeline	Date and Hour of Occurrence: 10:15 AM 1-5-18	Date and Hour of Discovery: Same
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Olivia Yu – Environmental Specialist	
By Whom? Ted Lilly – Flatrock Engineering and Environmental	Date and Hour: 11:50 AM 1-5-18 (Left a message) 12:45 PM 1-5-18 (Spoke to Olivia)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
No watercourse was impacted.

APPROVED

By Olivia Yu at 9:29 am, Apr 17, 2018



Describe Cause of Problem and Remedial Action Taken.*

A crude oil pipeline was struck when a utility crew was digging a hole for a new powerline pole. Crude oil was released to the surrounding soil.

Describe Area Affected and Cleanup Action Taken.*

Contaminated soil was excavated and placed on a tarp. The excavated soil will be hauled off and disposed of properly. Soil samples were collected from the excavated areas to determine if all impacted soils had been satisfactorily removed, or if additional corrective action is required. Once site had been cleared, it was backfilled to grade with clean fill dirt. Photographs attached.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Rory Gray	Approved by Environmental Specialist: 	
Title: <u>Engineering Analyst</u>	Approval Date: <u>4/17/2018</u>	Expiration Date: <u>xx/xx/xxxx</u>
E-mail Address: rgray@stakeholderms.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4-4-2018 Phone: 210-551-9014		

* Attach Additional Sheets If Necessary

1RP-4931

