

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Fasken Oil and Ranch, Ltd.	Contact	Jimmy Carlile
Address	303 W. Wall, Ste 1800 Midland, TX	Telephone No.	432 687-1777
Facility Name	Cabot Q SWD	Facility Type	Battery

Surface Owner	State	Mineral Owner	State	Lease No.
---------------	-------	---------------	-------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	7	15S	35E	1980	S	560	W	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	produced water	Volume of Release	130	Volume Recovered	120
Source of Release	injection line	Date and Hour of Occurrence		Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	3 pm 3/19/08	5 pm 3/19/08	
By Whom?	Jimmy Carlile	Date and Hour	8:15 am 3/20/08		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Pump vibration casued the injection line to come loose. Line re-applied and tightened.

Describe Area Affected and Cleanup Action Taken.*

Firewall inside tank battery area. No fluid escaped the firewall.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jimmy D. Carlile	Approved by District Supervisor:  ENVIRONMENTAL ENGINEER	
Title: Regulatory Affairs	Approval Date: 3-26-08	Expiration Date: 5-26-08
E-mail Address: jimmyc@for1.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/20/08 Phone: 432687-1777	VERTICAL DELINEATION IS REQUIRED DUE TO WATER DEPTH	1 RP # 1825

* Attach Additional Sheets If Necessary

