

3302 122nd Street
Lubbock, Texas 79423
Mailing Address:
P.O. Box 53427
Lubbock, Texas 79453
Phone: 806-771-8033
Fax: 806-687-6926
www.bccccorp.com



Texland Petroleum
State 'A' 29 Lease – Well #7
Unit K, Sec. 29-T18S-R38E, Lea Co., NM
Oil & Produced Water Spill
Affected Surface Area – 6,720 sq. ft. / .15 acre
GPS Coordinates: N32.71488 W103.17128

OCD Case Number 1RP-5025

APPROVED

By Olivia Yu at 4:13 pm, May 08, 2018

NMOCD will approve of the proposed delineation plan for 1RP-5025 with these conditions:

- 1) Sample locations no greater than 50 ft. apart.
- 2) Mark delineation sample locations with GPS coordinates on a scaled map.
- 3) Tabulate sample depths, field and lab data by sample IDs.

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Texland Petroleum-Hobbs, LLC	Contact	Vickie Smith
Address	777 Main St, Ste 3200, Fort Worth, TX 76102	Telephone No.	575-433-8395
Facility Name	State A 29	Facility Type	battery
Surface Owner	Fee	Mineral Owner	state
		API No.	30-025-22934

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	29	18S	38E	660'	North	1850'	West	Lea

Latitude _____ Longitude _____ NAD83

NATURE OF RELEASE

Type of Release	<1 BO + est 10-20 BPW	Volume of Release	<1 BO + 10-20 BPD	Volume Recovered	zero
Source of Release	flow line	Date and Hour of Occurrence	unknown	Date and Hour of Discovery	4/22/18 10:27 AM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

APPROVED

By Olivia Yu at 1:18 pm, Apr 24, 2018

Describe Cause of Problem and Remedial Action Taken.*

small washed out area of flow line failed, immediately turned off well

Describe Area Affected and Cleanup Action Taken.*

Skim oil and water flowed to low area on Conoco Phillips' caliche pad, Texland will use a back hoe to remove all contaminated caliche and replace with new/fresh caliche

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Vickie Smith</i>		OIL CONSERVATION DIVISION	
Printed Name: Vickie Smith		Approved by Environmental Specialist: <i>oy</i>	
Title: Regulatory Analyst		Approval Date: 4/24/2018	Expiration Date:
E-mail Address: vsmith@texpetro.com		Conditions of Approval: see attached directive	Attached <input checked="" type="checkbox"/>
Date: 4/23/18 Phone: 575-433-8395			

* Attach Additional Sheets If Necessary

1RP-5025

nOY1811448112

pOY1811448332

3302 122nd Street
Lubbock, Texas 79423
Mailing Address:
P.O. Box 53427
Lubbock, Texas 79453
Phone: 806-771-8033
Fax: 806-687-6926
www.bccccorp.com



May 1, 2018


**Texland Petroleum
State 'A' 29 Lease – Well #7
Unit K, Sec. 29-T18S-R38E, Lea Co., NM
Oil & Produced Water Spill
Affected Surface Area – 6,720 sq. ft. / .15 acre
GPS Coordinates: N32.71488 W103.17128**


OCD Case Number 1RP-5025

Release Characterization / Delineation Plan

On April 26, 2018, BCC, Inc. conducted a site assessment of an oil and produced water release that originated from a ruptured flowline running from Texland Petroleum's State 'A' 29 Well #7. The total volume released was less than 20 barrels of produced water, which included skim oil. The affected surface area is located 40 yards southeast of the State 'A' 29 Tank Battery on a caliche pad inside the city limits of Hobbs, New Mexico. All of the affected surface areas were mapped and tracked by GPS with the square footage totaling 6,720 square feet, or .15 acre. The affected soils do not contain any free liquids and they are not impacting any wildlife or vegetation. According to the New Mexico Office of the State Engineer, the average depth to ground water below land surface at this site is 62 feet. The horizontal distance from the nearest surface water body is >1,000 feet.

With the approval from the NMOCD, Texland Petroleum and BCC, Inc. would like to begin delineating this site both horizontally and vertically to determine the extent of the impacted soil. On-site field testing of the soil will be performed, which will include both chloride and TPH analysis. Split soil samples will be laboratory analyzed for confirmation of the field testing results on the bottom and sidewall sample locations. A complete BTEX analysis will be included on all of the laboratory samples. Once the laboratory analysis has been received, a complete corrective action plan will be submitted to the NMOCD for approval before any remediation work begins.


Paul Porter
Vice President
BCC, Inc.



★ Texland State A 29 #7

© 2018 Google

Google earth

Texland Petroleum
State 'A' 29 Lease - Well #7
Oil & Produced Water Spill
Affected Surface Area - 6,720 sq. ft. / .15 acre
GPS Coordinates: N32.71488
W103.17128



©2018 Google

Google earth



Imagery Date: 11/2/2017

lat 32.714965° lon -103.171692° elev 3653 ft

Eye alt 4026 ft

Texland Petroleum
State 'A' 29 Lease - Well #7
Oil & Produced Water Spill
Affected Surface Area - 6,720 sq. ft. / .15 acre
GPS Coordinates: N32.71488
W103.17128



Texland State A 29 #7



© 2018 Google

Google earth



Imagery Date: 11/2/2017

lat 32.714935° lon -103.171606° elev 3653 ft

Eye alt 4061 ft

TEXLAND PETROLEUM -
HOBBS LLC.
STATE A-29 BATTERY
UNIT K, SEC. 29-T18S-R38E
LEA COUNTY, NM

IN CASE OF EMERGENCY
CALL
TEXLAND PETROLEUM
(806) 894-4316

04 26 2018



04 26 2018



04 26 2018



04 26 2018



04 26 2018



04 26 2018



04 26 2018



04 26 2018



04 26 2018