

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	SPECIAL ENERGY CORP. (138008)	Contact	DON TERRY
Address	P.O. DRAWER 369, STILLWATER, OK 74076	Telephone No.	405.377.1177
Facility Name	CARTER #001 (30-025-04621)	Facility Type	PRODUCING GAS WELL LEASE LOCATION

Surface Owner	ANTLEY SNYDER	Mineral Owner	CARTER FAMILY MINERALS	API No.	30-025-04621
---------------	---------------	---------------	------------------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	12	21S	36E	1980	NORTH	1980	EAST	LEA

Latitude 32.4952393

Longitude -103.2167969 NAD83

NATURE OF RELEASE

Type of Release	OILY SALTWATER	Volume of Release	100 BBLS	Volume Recovered	5 BBLS
Source of Release	UNIDENTIFIED VACUUM TRANSPORT	OCCURRENCE:	02/27/18 0000	Discovery:	02/27/18 1000 HRS.
Was Immediate Notice Given?	☒ Yes ☐ No ☐ Not Required				
By Whom?	BENNY BRITO AND SAM BLEVINS (575.602.5512)				
Was a Watercourse Reached?	☐ Yes ☒ No				
If a Watercourse was Impacted, Describe Fully.*	N/A				

APPROVED

By Olivia Yu at 10:49 am, May 09, 2018


Describe Cause of Problem and Remedial Action Taken.*

UNIDENTIFIED VACUUM TRUCK ILLEGALLY UNLOADED +/-100 BBLS OF OILY SALTWATER FROM TRANSPORT ONTO AND AROUND THE SPECAIL ENERGY CORP CARTER #001 SURFACE LEASE. GUNS UP TRUCKING VACCUMED +/-5 BBLS OF FLUID 02/27/18.

Describe Area Affected and Cleanup Action Taken.*

AREA AFFECTED = 60' X 50' (3,000 SQ.FT) STRADDLING AN ELEVATED EAST-WEST ORIENTATED ENERGY TRANSFER METER RUN. PER OLIVIA YU, HIRED BACKHOE TO CLEAN UP AFFECTED AREA AND PILED CONTAMINATED SOIL ON LOCATION. SURFACE, ONE FOOT AND TWO FOOT SAMPLES WERE GATHERED AND ANALYZED BY CARDINAL LABS. PER OLIVIA YU AN ADDITONAL 8"-10" OF SOIL WAS REMOVED AND ANALYZED BY CARDINAL LABS. RESULTS ACCEPTABLE TO OLIVIA YU. REQUEST IS HEREBY MADE TO BACKFILL AREA AND CLOSURE OF INCIDENT.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: DAVID A. EYLER		Approved by Environmental Specialist: 	
Title: AGENT	Approval Date: 5/9/2018	Expiration Date: xx/xx/xxxx	
E-mail Address: DEYLER@MILAGRO-RES.COM	Conditions of Approval:		Attached ☐
Date: 05/08/18	Phone: N432.687.3033		

* Attach Additional Sheets If Necessary

1RP-4989

