

**From:** Tucker, Shelly  
**To:** [Yu, Olivia, EMNRD](#)  
**Cc:** [Ben J. Arguijo](#); [Hernandez, Christina, EMNRD](#); [Wade Dittrich](#); [Duskie Bennett](#); [Todd Roberson](#)  
**Subject:** Re: [EXTERNAL] RE: Backfill Request - Red Tank 24 Federal 1 & 2 CTB (1RP-4762)  
**Date:** Friday, June 8, 2018 1:06:07 PM

---

## BLM concurs with NMOCD approval and stipulations.

**NOTE: LPC Timing Stipulations are in effect - from March 1st through June 15th. Please plan remedial activities accordingly. Check for African Rue...treat (before it gets out of control).**

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

*Shelly J Tucker*

Environmental Protection Specialist  
O&G Spill/Release Coordinator

575.234.5905 - Direct  
575.361.0084 - Cellular  
575.234.6235 - Emergency Spill Number

[stucker@blm.gov](mailto:stucker@blm.gov)

### **Bureau of Land Management**

620 E. Greene St  
Carlsbad, NM 88220

The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. **In such an event a site does not achieve successful restoration, or future issues with contaminants are encountered, the operator will be asked to address these issues until they are fully mitigated and the location is successfully reclaimed.** In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

**Confidentiality Warning:** This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Tue, Jun 5, 2018 at 3:14 PM, Yu, Olivia, EMNRD <[Olivia.Yu@state.nm.us](mailto:Olivia.Yu@state.nm.us)> wrote:

Mr. Arguijo:

Yes, please. NMOCD grants backfill approval for 1RP-4762 with the condition of 3 additional confirmation samples for laboratory analyses: West sidewall; East & West sidewalls of the area represented by Floor 2 (i.e., between 1 ft. and 4 ft. excavated areas). Please provide field data if available.

Like approval from BLM required.

Please note that there is an additional Environmental Specialist in District 1. Please include Christina Hernandez in communications and report submittals.

Thanks,

Olivia

**From:** Ben J. Arguijo <[ben@trinityoilfieldservices.com](mailto:ben@trinityoilfieldservices.com)>  
**Sent:** Tuesday, June 5, 2018 2:50 PM  
**To:** Yu, Olivia, EMNRD <[Olivia.Yu@state.nm.us](mailto:Olivia.Yu@state.nm.us)>  
**Cc:** Tucker, Shelly <[stucker@blm.gov](mailto:stucker@blm.gov)>; Wade Dittrich <[wade\\_dittrich@oxy.com](mailto:wade_dittrich@oxy.com)>; Duskie Bennett <[duskie@trinityoilfieldservices.com](mailto:duskie@trinityoilfieldservices.com)>; Todd Roberson <[todd@trinityoilfieldservices.com](mailto:todd@trinityoilfieldservices.com)>  
**Subject:** Re: Backfill Request - Red Tank 24 Federal 1 & 2 CTB (1RP-4762)

Olivia,

Sorry for the delay in response. We have a chloride field test from the west wall with a concentration of 332 mg/kg, and olfactory/visual senses indicated that TPH and BTEX were below the RRALs. Do we need to submit a sample for analysis?

Ben

Ben J. Arguijo

Environmental Project Manager

Trinity Oilfield Services

P.O. Box 2587

Hobbs, NM 88241

(575)390-7208

[ben@trinityoilfieldservices.com](mailto:ben@trinityoilfieldservices.com)

On Mon, May 14, 2018 at 11:30 AM, Yu, Olivia, EMNRD <[Olivia.Yu@state.nm.us](mailto:Olivia.Yu@state.nm.us)>

wrote:

Mr. Arguijo:

In reviewing the sample map for 1RP-4762, there was no location indicated for the West wall, West of SP-2. Was one taken for laboratory analyses? If not, are there field data to verify that the indicated outline was the western edge of the release area?

Thanks,

Olivia

**From:** Ben J. Arguijo <[ben@trinityoilfieldservices.com](mailto:ben@trinityoilfieldservices.com)>  
**Sent:** Monday, May 14, 2018 9:23 AM  
**To:** Yu, Olivia, EMNRD <[Olivia.Yu@state.nm.us](mailto:Olivia.Yu@state.nm.us)>; Tucker, Shelly <[stucker@blm.gov](mailto:stucker@blm.gov)>  
**Cc:** Wade Dittrich <[wade\\_dittrich@oxy.com](mailto:wade_dittrich@oxy.com)>; Duskie Bennett <[duskie@trinityoilfieldservices.com](mailto:duskie@trinityoilfieldservices.com)>; Todd Roberson <[todd@trinityoilfieldservices.com](mailto:todd@trinityoilfieldservices.com)>  
**Subject:** Backfill Request - Red Tank 24 Federal 1 & 2 CTB (1RP-4762)

Olivia/Shelly,

Attached please find the "Environmental Site Summary & Backfill Request" for the Red Tank 24 Federal 1 & 2 CTB release site (1RP-4762).

If you have any questions, please do not hesitate to contact me.

Respectfully,

Ben J. Arguijo

Ben J. Arguijo

Environmental Project Manager

Trinity Oilfield Services

P.O. Box 2587

Hobbs, NM 88241

(575)390-7208

[ben@trinityoilfieldservices.com](mailto:ben@trinityoilfieldservices.com)