

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Plains Pipeline	Contact Amber Groves	
Address 1911 Connie Rd, Carlsbad NM 88220	Telephone No. (575)200-5517	
Facility Name Mewbourne Marathon 15 PA	Facility Type Tank Battery	
Surface Owner Kenneth Smith	Mineral Owner BLM	API No.

LOCATION OF RELEASE

Unit Letter P	Section 15	Township 20S	Range 34E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.56721 Longitude -103.540506 NAD83

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 30 bbls	Volume Recovered 2 bbls
Source of Release 1/2 inch valve	Date and Hour of Occurrence 2/1/2018 @ 1:01 PM	Date and Hour of Discovery 2/1/2018 @ 1:01 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Voicemail to Olivia Yu	
By Whom? Amber Groves	Date and Hour 2/1/2018 @ 3:47 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

APPROVED

By Olivia Yu at 11:33 am, Jun 20, 2018



Describe Cause of Problem and Remedial Action Taken.*

1/2" valve on top of a tee with a test port with 3/8" tubing running to the sump box was tampered with and forced open.

Describe Area Affected and Cleanup Action Taken.*

The impacted area is contained to the pad and was remediated per current NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature 	OIL CONSERVATION DIVISION	
Printed Name: Amber Groves	Approved by Environmental Specialist: 	
Title: Remediation Coordinator	Approval Date: 6/20/2018	Expiration Date:
E-mail Address: algroves@paalp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/5/2018 Phone: (575)200-5517		

* Attach Additional Sheets If Necessary

1RP-4964