

Midland Office 11806 Jordy Road Midland TX 79707 1(432)262-8090

CHEVRON NORTH AMERICA EXPLORATION AND PRODUCTION COMPANY 6301 DEAUVILLE BLVD.
MIDLAND, TX 79706

CHEVRON NORTH AMERICA EXPLORATION AND PRODUCTION COMPANY SALADO DRAW FRAC POND REPAIR TRANSFER CARE CUSTODY & CONTROL

With the completion of the visual inspection, lining repair, and completion of the Quality Control Turn over Document, KS Industries transfers of care, custody and control to Chevron for repair on the lining on Salado Draw Frac Pond.

Acceptance of care, custody and control, means that Chevron accepts the Turn over Document for KS Industries Salado Draw Frac pond repair.

Signature below signifies CHEVRON NORTH AMERICA EXPLORATION AND PRODUCTION COMPANY ownership and acceptance of KS Industries/MUSTANG installed repaired areas.

Representative, Chevron,	Date: 7/11/2018
Representative, Mustang	Date: 7/11/18
Joe A Cortez, KSILLC, QC Manager	Date: 7/11/2018
Longinus Alexander, KSILLC, Superintendent	Date: 7/1/18.

CA License #473011 7/11/2018









