

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Plains Pipeline	Contact Amber Groves	
Address 1911 Connie Rd, Carlsbad NM 88220	Telephone No. (575)200-5517	
Facility Name COG Boone 16 2H to Segment 2	Facility Type Tank Battery	
Surface Owner Merchant Livestock	Mineral Owner State	API No.

#### LOCATION OF RELEASE

Unit Letter O	Section 16	Township 21S	Range 33E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.4724 Longitude -103.5752 NAD83

#### NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 7 bbls	Volume Recovered 4 bbls
Source of Release 1/2 inch Nipple	Date and Hour of Occurrence 4/5/2018 @ 4:04 PM	Date and Hour of Discovery 4/5/2018 @ 4:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Voicemail to Olivia Yu	
By Whom? Amber Groves	Date and Hour 4/6/2018 @ 9:16 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**APPROVED**

By CHernandez at 1:32 pm, Aug 03, 2018



Describe Cause of Problem and Remedial Action Taken.\*

1/2" nipple broke upstream of the 1/2" valve on the chemical injection point.

Describe Area Affected and Cleanup Action Taken.\*

Impacted area includes the pad and overspray in the pasture. All areas were remediated as per current NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Amber Groves	Approved by Environmental Specialist: 	
Title: Remediation Coordinator	Approval Date: 8/3/2018	Expiration Date: xx/xx/xx
E-mail Address: algroves@paalp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/5/2018	Phone: 575-200-5517	

\* Attach Additional Sheets If Necessary

1RP-5014