

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate
District Office in accordance
With 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Plains Pipeline LP	Contact	Camille Bryant
Address	505 N. Big Spring Suite 600, Midland, TX 79701	Telephone No.	(575) 441-1099
Facility Name	Mewbourne Mad Dog 26 MP State Com #001H	Facility Type	Lact Unit
Surface Owner	NMSLO	Mineral Owner	NMSLO
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	26	23S	34E					Lea

Latitude N 32.2687600° Longitude W 103.4482740° NAD83

NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	9 bbls	Volume Recovered	6 bbls
Source of Release	Triplex Pump	Date and Hour of Occurrence	08/19/2018 @ 14:45	Date and Hour of Discovery	08/19/2018 @ 14:45
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Voicemail to Olivia Yu		
By Whom?	Camille Bryant	Date and Hour	08/20/2018 @ 12:40		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



RECEIVED

By CHernandez at 5:12 pm, Aug 21, 2018

Describe Cause of Problem and Remedial Action Taken.* Mechanical failure of Triplex pump resulted in a release of crude oil. Released fluids were confined to the secondary containment and caliche pad of the facility.

Describe Area Affected and Cleanup Action Taken. The released crude oil impacted the bermed lact unit and adjacent production pad. The impacted area will be remediated as per applicable NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Camille Bryant	Approved by Environmental Specialist::	
Title: Remediation Supervisor	Approval Date: 8/21/2018	on Date:
E-mail Address: cjbryant@paalp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 08/21/2018 Phone: (575) 441-1099	NMAC 19.15.29 effective August 14, 2018. Complete release characterization before any significant remediation.	

* Attach Additional Sheets If Necessary

1RP-5168

nCH1823364998

pCH1823362780

fCH1823364176