

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Plains Pipeline, LP	Contact Camille Bryant
Address 505 N. Big Spring, Suite 600, Midland, TX 79701	Telephone No. 575-441-1099
Facility Name Mewbourne Cabra Nino 11 B3NC State Com #1H	Facility Type Lact Unit

Surface Owner NMSLO	Mineral Owner NMSLO	API No.
---------------------	---------------------	---------

LOCATION OF RELEASE

Unit Letter N	Section 11	Township 22S	Range 34E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.3992239 Longitude -103.4432368 NAD83

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 35 bbls	Volume Recovered 11 bbls
Source of Release Tubing on the Back Pressure Valve	Date and Hour of Occurrence 8/21/2018 @ 9:35 AM	Date and Hour of Discovery 8/21/2018 @ 9:35 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Olivia Yu	
By Whom? Camille Bryant	Date and Hour 8/22/2018 @ 7:12 AM by voicemail	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Tubing failure on the back pressure valve.

Describe Area Affected and Cleanup Action Taken.*

Impacted area includes lact unit, approximately 2950 square feet production pad/lease road and approximately 3852 square feet in the pasture. Release area will be remediated per current NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Camille Bryant	Approved by Environmental Specialist: 	
Title: Remediation Supervisor	Approval Date: 8/23/2018	Expiration Date:
E-mail Address: cjbrant@paalp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/22/2018 Phone: (575)441-1099	NMAC 19.15.29 effective August 14, 2018. Complete release characterization before any significant remediation.	

* Attach Additional Sheets If Necessary

1RP-5172

nCH1823548255

pCH1823547376