

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	OGRID# [229137]	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: JAGUAR 18 STATE #002H	Facility Type: Well	
Surface Owner: State	Mineral Owner:	API No. 30-025-41428

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	18	23S	33E	330'	South	1980'	West	Lea

Latitude 32.29842

Longitude 103.61335

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 15bbls of Oil & 25bbls of Produced Water	Volume Recovered: 10bbls of Oil & 20bbls of Produced Water
Source of Release: Wellhead	Date and Hour of Occurrence: 3/29/2017 07:00 AM	Date and Hour of Discovery: 3/29/2017 07:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Yu - NMOCD / Ms. Groves - SLO	
By Whom? Robert Grubbs Jr	Date and Hour: Thu 3/30/2017 9:50 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

APPROVED

By Olivia Yu at 10:11 am, Sep 12, 2018

Describe Cause of Problem and Remedial Action Taken.*



The release was caused by a valve that was left half way open on the north casing valve. Close valve.

Describe Area Affected and Cleanup Action Taken.*

The release was contained on the wellpad.

Remediation activities were conducted in accordance with an NMOCD and NMSLO-approved *Workplan* and/or associated correspondence with respective regulatory representatives. Please reference the *Workplan* dated September 2, 2017, and *Remediation Summary and Closure Report* dated February 27, 2018 for additional details regarding remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Rebecca Haskell	Approved by Environmental Specialist: 	
Title: Senior HSE Coordinator	Approval Date: 9/12/2018	Expiration Date: xx/xx/xxxx
E-mail Address: rhaskell@concho.com	Conditions of Approval: NMSLO approval	Attached <input type="checkbox"/>
Date: March 20, 2018	Phone: 432-683-2372	

* Attach Additional Sheets If Necessary

1RP-4667