

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC OGRID # 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: Gunslinger 11 Federal Com #001	Facility Type: Tank Battery
Surface Owner: Federal	Mineral Owner: API No. 30-025-36797

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	11	20S	33E	810	South	660	West	Lea

Latitude 32.582877 Longitude -103.640467

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 25 bbls Oil & 15 bbls PW	Volume Recovered: 20 bbls Oil & 10 bbls PW
Source of Release: Heater Treater	Date and Hour of Occurrence: March 18, 2017 9:30 am	Date and Hour of Discovery: March 18, 2017 9:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

APPROVED

By Olivia Yu at 8:29 am, Sep 13, 2018

Describe Cause of Problem and Remedial Action Taken.*

The release was caused by pressure valve failure on a heater treater, causing fluids to be released through the relief valve. The pressure valve was replaced.

Describe Area Affected and Cleanup Action Taken.*

The release was within and unlined facility with overspray on the adjacent pasture. A vacuum truck was dispatched to remove all freestanding fluids.

Remediation activities were conducted in accordance with an NMOCD and BLM-approved *Workplan* and/or associated correspondence with respective regulatory representatives. Please reference the *Workplan* dated September 7, 2017, and *Remediation Summary and Soil Closure Report* dated March 2018 for additional details regarding remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>	OIL CONSERVATION DIVISION	
Printed Name: Rebecca Haskell	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior HSE Coordinator	Approval Date: 9/13/2018	Expiration Date: xx/xx/xxxx
E-mail Address: rhaskell@concho.com	Conditions of Approval: BLM approval	Attached <input type="checkbox"/>
Date: March 21, 2017 Phone: 432-683-7443		

* Attach Additional Sheets If Necessary

1RP-4651