

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Abo Empire, LLC	Contact	Dan Lewis
Address	PO Box 900, Artesia, NM 88211-0900	Telephone No.	575-736-3082
Facility Name	Angle State #3	Facility Type	Battery
Surface Owner	Mineral Owner	API No. 30 025 25347	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	9	17S	34E	330	South	330	West	Lea

Latitude 32.847078° Longitude -103.563366 NAD83

NATURE OF RELEASE

Type of Release Produced	Water and a little oil	Volume of Release	40.5W 3.5 Oil	Volume Recovered	
Source of Release	Gun Barrel	Date and Hour of Occurrence	3/15/17	Date and Hour of Discovery	3/15/17PM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

APPROVED

By Olivia Yu at 9:08 am, Sep 14, 2018



Describe Cause of Problem and Remedial Action Taken.*

The wind caused the Waterleg on the Gun Barrel to come loose, breaking off the main water valve at the bottom of the gun barrel. That caused the Gun Barrel to completely drain inside the containment area.

Describe Area Affected and Cleanup Action Taken.*

Removed the standing produced water and oil. Removed the contaminated soil and hauled it to CRI Land Farm. Repaired the fencing around the Tank Battery containment area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Dan S. Lewis	Approved by Environmental Specialist: 		
Title: CFO	Approval Date: 9/14/2018	Expiration Date: xx/xx/xxxx	
E-mail Address: dan@abopet.com	Conditions of Approval: NMSLO approval		Attached <input type="checkbox"/>
Date: 5-8-17	Phone: 575-736-3082		

* Attach Additional Sheets If Necessary

1RP-4670