

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC [OGRID] 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: KING TUT FEDERAL #001H (1RP-4843)	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-025-41542
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	30	24S	32E	190'	North	330'	West	Lea [sic]

Latitude 32.21515 Longitude -103.72276 NAD83

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 5 bbls pw	Volume Recovered: 4 bbls pw
Source of Release: Flowline/Pipeline	Date and Hour of Occurrence: 10-10-2017 4:00 pm	Date and Hour of Discovery: 10-10-2017 4:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

APPROVED

By Olivia Yu at 3:17 pm, Sep 14, 2018

Describe Cause of Problem and Remedial Action Taken.*

The release occurred when a hole developed in the flowline. The damaged portion of the flowline has been removed and replaced.

Describe Area Affected and Cleanup Action Taken.*

The release occurred alongside the lease road in the pasture. The line was isolated until repaired.

Remediation activities were conducted in accordance with applicable NMOCD and BLM Guidelines. Impacted soil affected above the NMOCD Recommended Remediation Action Levels was excavated and transported to and NMOCD-approved disposal facility. Laboratory analytical results from excavation confirmation soil samples and associated delineation soil samples indicated BTEX, TPH and chloride concentrations were below the NMOCD RRAL. Upon collecting the required excavation confirmation soil samples, the excavated area was backfilled with locally sourced, non-impacted material. Please reference the Remediation Summary and Soil Closure Request, dated April 2018, for additional details regarding remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
	Approved by Environmental Specialist: 	
Printed Name: Becky Haskell	Approval Date: 9/14/2018	Expiration Date: xx/xx/xxxx
Title: HSE Coordinator	Conditions of Approval:	
E-mail Address: rhaskell@concho.com	BLM approval	Attached <input type="checkbox"/>
Date: May 3, 2018 Phone: 432-818-2372		

* Attach Additional Sheets If Necessary

1RP-4843