

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	nCH1826343790
District RP	1RP-5195
Facility ID	
Application ID	pCH1826344217

## Release Notification

### Responsible Party

Responsible Party Vanguard Operating, LLC	OGRID 258350
Contact Name Brent White	Contact Telephone 505-918-0669
Contact email bwhite@vnrenergy.com	Incident # (assigned by OCD)
Contact mailing address 4001 Penbrooke Suite 201 Odessa, TX 79762	

### Location of Release Source

Latitude 32.867627 Longitude -103.297600  
(NAD 83 in decimal degrees to 5 decimal places)

Site Name C.S. Caylor SR Estate #3	Site Type Tank Battery
Date Release Discovered 9-3-2018	API# (NCH1826343790 C.S. CAYLOR SR ESTATE #3 @ 30-025-05430)

Unit Letter	Section	Township	Range	County
D	6	17S	37E	Lea

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: \_\_\_\_\_)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
X Produced Water	Volume Released (bbls) 100	Volume Recovered (bbls) 250 Including rain water
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	X Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release Lightning struck the tank partially burning and releasing 100 bbls of produced water inside of a lined containment.


State of New Mexico  
Oil Conservation Division

Incident ID	nCH1826343790
District RP	1RP-5195
Facility ID	
Application ID	pCH1826344217

Was this a major release as defined by 19.15.29.7(A) NMAC?  X Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? Greater than 25 bbls.
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Yes by Chuck Johnston to Olivia Yu and Christina Hernandez 9-4-2018 3:50 pm email.	

### Initial Response

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:   	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Chuck Johnston</u> Signature:  email: <u>cjohnston@vnrenergy.com</u>	Title: <u>EHS Operations Specialist</u> Date: <u>9-10-2018</u> Telephone: <u>432-202-4771</u>
<b>OCD Only</b> Received by: <b>RECEIVED</b> <u>By CHernandez at 11:23 am, Sep 20, 2018</u>	
Date: _____	