

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Incident ID	NOY1826748976
District RP	1RP-5199
Facility ID	fOY1826747980
Application ID	pOY1826748631

Release Notification

Responsible Party

Responsible Party	Mesquite SWD, Inc.	OGRID	161968
Contact Name	Riley Neatherlin	Contact Telephone	575-706-7288
Contact email	riley@mesquiteswd.net	Incident # (assigned by OCD)	NOY1826748976
Contact mailing address	PO Box 1479, Carlsbad, NM 88221-1479		

Location of Release Source

Latitude 32.051807 Longitude -103.683153
(NAD 83 in decimal degrees to 5 decimal places)

Site Name	Mesquite 10" from Paduca Booster to Salado	Site Type	Buried 10" produced water line
Date Release Discovered	09/13/2018	API# (if applicable)	

Unit Letter	Section	Township	Range	County
N	9	26S	32E	LEA

Surface Owner: State Federal Tribal Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 200 BBLS	Volume Recovered (bbls) 0
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

Mewbourne Oi Company was installing a road bore under C1. While drilling the road bore, Mesquite's 10" line was struck.

Incident ID	NOY1826748976
District RP	1RP-5199
Facility ID	fOY1826747980
Application ID	pOY1826748631

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? Volume
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? No Contact Riley Neatherlin 575-706-7288	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury


- The source of the release has been stopped.
- The impacted area has been secured to protect human health and the environment.
- Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.
- All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Melanie Wilson Title: Regulatory Analyst

Signature:  Date: 09/14/2018

email: mjp1692@gmail.com Telephone: 575-914-1461

OCD Only

Received by:

RECEIVED

By Olivia Yu at 1:15 pm, Sep 24, 2018

Date: _____