Mr. Garcia:

Were confirmation sidewall and bottom samples taken before placement of the 20 mil liner at the Central location and backfilling for 1RP-4582? Please be advised that confirmation samples are generally required before approval for backfilling or closure.

Thanks, Olivia

From: eric garcia [mailto:ericgarcia62@hotmail.com]
Sent: Thursday, August 3, 2017 4:19 PM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; Groves, Amber <agroves@slo.state.nm.us>; eric garcia <ericgarcia62@hotmail.com>
Subject: Site Closure Report 1RP-4582

Olivia,

The following attachments contains the C-141 Final Report Form and the Closure Report for Read and Steven Inc., Shell State #3 1RP-4582.

Thank You,

Eric Garcia

Republic Backhoe Service LLC.