

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nCH1828463241
District RP	1RP-5223
Facility ID	fCH1828462751
Application ID	pCH1828463804

Release Notification

Responsible Party

Responsible Party Plains Pipeline, L.P.	OGRID 713291
Contact Name Amber Groves	Contact Telephone 575-200-5517
Contact email algroves@paalp.com	Incident # NCH1828463241 COG STRATOJET 31 STATE COM @ FCH1828462751vvvv
Contact mailing address 1911 Connie Road, Carlsbad NM 88220	

Location of Release Source

Latitude 32.523582

Longitude -103.494174

(NAD 83 in decimal degrees to 5 decimal places)

Site Name COG Stratojet 31 State Com #006H	Site Type LACT Unit
Date Release Discovered 9/25/2018	API# (if applicable)

Unit Letter	Section	Township	Range	County
O	31	20S	35E	Lea

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☒ Private (Name: S&S-Patrick Sims)

State Minerals

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls) 20 bbls	Volume Recovered (bbls) 15 bbls
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

Valve left open by a second party.

State of New Mexico
Oil Conservation Division

Incident ID	nCH1828463241
District RP	1RP-5223
Facility ID	fCH1828462751
Application ID	pCH1828463804

Was this a major release as defined by 19.15.29.7(A) NMAC?

☐ Yes ☒ No

If YES, for what reason(s) does the responsible party consider this a major release?

If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?
Notification was given to Olivia Yu at NMOCD by phone on 9/26/2018 at 8:01 am.

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

- ☒ The source of the release has been stopped.
- ☒ The impacted area has been secured to protect human health and the environment.
- ☒ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.
- ☒ All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Amber Groves

Title: Remediation Coordinator

Signature: Amber Groves

Date: 10/3/2018

email: algroves@paalp.com

Telephone: 575-200-5517

OCD Only

RECEIVED

Received by: **By CHernandez at 5:19 pm, Oct 11, 2018**

Amber L Groves

From: James L Papstein
Sent: Tuesday, October 02, 2018 7:06 AM
To: Amber L Groves; Michael S Hicks
Cc: Camille J Bryant
Subject: RE: COG Stratojet 31 State Com #002H

20 barrels released, 15 barrels recovered for disposal, 5 barrels lost.

Length	Width	Depth		Volume Barrels
15	8	11	0.0154	20.328

James (Jim) Papstein
Plains All American
432-209-2770
