

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nCH1828467837
District RP	1RP-5226
Facility ID	fCH1828467406
Application ID	pCH1828468053

Release Notification

Responsible Party

Responsible Party	Oxy USA Inc.	OGRID	16696
Contact Name	Wade Dittrich	Contact Telephone	(575) 390-2828
Contact email	Wade_Dittrich@oxy.com	Incident #	NCH1828467837 SOUTH MATTIX FEDERAL FOWLER SWD @ FCH1828467406
Contact mailing address	PO Box 4294; Houston, TX 77210		

Location of Release Source

Latitude N 32.217304 Longitude W-103.149583
(NAD 83 in decimal degrees to 5 decimal places)

Site Name	SOUTH MATTIX FEDERAL FOWLER SWD	Site Type	SWD
Date Release Discovered	09/19/2018	API# (if applicable)	

Unit Letter	Section	Township	Range	County
J	15	24S	37E	LEA COUNTY, NM

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☒ Private (Name: _____)

Federal Minerals

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls) 330	Volume Recovered (bbls) 100
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 492	Volume Recovered (bbls) 70
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

Lightning struck tanks and caused fire and released fluid


State of New Mexico
Oil Conservation Division

Incident ID	nCH1828467837
District RP	1RP-5226
Facility ID	fCH1828467406
Application ID	pCH1828468053

Was this a major release as defined by 19.15.29.7(A) NMAC? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? WADE DITTRICH made notification by e-mail or via phone: OLIVIA YU , CHRISTINA HERNANDEZ-NMOCD
---	--

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: 	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: Wade Dittrich Signature:  email: wade_dittrich@oxy.com	Title: Environmental Specialist Date: 9/25/2018 Telephone: (575) 390-2828
<div style="border: 1px solid black; padding: 5px; display: inline-block;"> RECEIVED By CHernandez at 6:57 pm, Oct 11, 2018 </div>	
Received by: _____ Date: _____	