

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Wishbone Texas Operating, LLC	Contact Wayne Dixon	
Address 10613 W San Houston Prkwy N Suite 4000	Telephone No. 432 556 5923	
Facility Name HH Harris #2	Facility Type Oil Well	
Surface Owner HH Harris	Mineral Owner	API No. 30-025-20931

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	35	12S	38E	650	South	1800	East	Lea

Latitude 32.2297 Longitude -103.0658

NATURE OF RELEASE

Type of Release Produced Water/Oil	Volume of Release 40 bbls	Volume Recovered 20 bbls
Source of Release Flow line leak	Date and Hour of Occurrence 19Dec16	Date and Hour of Discovery 20Dec16
Was Immediate Notice Given? x Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Christina Lynch voicemail/Tomas Obering voicemail	
By Whom? David Massey	Date and Hour 20Dec16 1600hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

APPROVED

By Olivia Yu at 8:19 am, Oct 24, 2018



Describe Cause of Problem and Remedial Action Taken.*

Ice plug in flowline broke in bend, added a 45 degree fitting in bend to relieve tension in curve.

Describe Area Affected and Cleanup Action Taken.*

The impacted area consisted of the area immediately to the north of the well head on the location and in the pasture. Immediate action to recover free standing fluid and saturated soil was done upon discovery. Remediation of the impacted area was completed using the dig and haul method. Various soil samples were obtained, analyzed, and submitted to NMOCD for review. Backfill approval was requested and approved. The excavated area was backfilled with fresh soil from a local source.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Wayne Dixon	Approved by Environmental Specialist: 	
Title: Production Foreman	Approval Date: 10/24/2018	Expiration Date: xx/xx/xxxx
E-mail Address: wdixon@wishboneep.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 22Jun18	Phone: 432 556 5923	

* Attach Additional Sheets If Necessary

NMOCD IRP-4543