State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

			T •	BT									
			Rel	ease Notific	eatio	n and Co	orrective A	ction					
						OPERA '	ГOR	[Initi	al Report	\bowtie	Final Report	
Name of Co	ompany					Contact							
EOG Y Res		с.			Amber Griffin								
Address					Telephone No.								
105 S. 4th St	treet Artes	sia, NM 882			575-748-4111								
Facility Nar		,			Facility Type								
Willie BNW					Well & Tanks								
Surface Ow	ner		Mineral C	wner					API No.				
State			State		30-0				25-36684				
LOCATION OF RELEASE													
Unit Letter	Section Township Range								/West Line County				
A	6	12S	35E	770		North	950		ast	County Lea			
71		120	550	110		Horm	550		ası	Lua			
	1	1	1				L	1		1			
Latitude <u>33.3128738</u> Longitude <u>103.4417419</u>													
NATURE OF RELEASE													
Type of Relea	Type of Release Volume Recovered												
Produced Water & Crude Oil						15 B/PW, 30 B/O			5 B/PW, 15 B/O				
Source of Release										nd Hour of Discovery			
Oil tank over	flow				7/3/2016; AM 7/3/201								
Was Immedia	ate Notice C	Given? 🛛 Y	No 🔲 Not Requ	ired	If YES, To Whom? Jamie Keyes								
By Whom? R	obert Ashe	r			Date and Hour: 7/3/2016 - 6:02 PM, via email								
Was a Watero			No		If YES, Volume Impacting the Watercourse.								
If a Watercou	irse was Im	pacted, Descr	ibe Fully.*	* N/A									
Describe Cause of Problem and Remedial Action Taken.*													
The separator dump on location experienced problems and dumped produced water into the crude oil tanks. This resulted in the crude oil tanks overfilling.													
The well was shut in, vacuum trucks were called, and visibly impacted soils were excavated and hauled to a NMOCD approved facility. The overspray													
area behind the battery was sprayed with a Micro-Blaze/water mixture.													
Describe Area Affected and Cleanup Action Taken: The affected area is approximately 40' x 70' within an unlined bermed battery. There was also minor overspray behind the tank battery. Vertical													
				se area and analys s 20) a Final Repo									
above the RR	AI's a wor	k nlan will be	submitte	$\frac{1}{20}$ to the OCD Der	11, C-14	Fround Wate	$r_{\rm c} < 50^{\circ}$ par Chav	ron/Toy	ing closure	Mon Woll	lytical I	results are	
above the RRAL's a work plan will be submitted to the OCD. Depth to Ground Water: <50' per Chevron/Texaco Trend Map, Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 20. EOG Y requests closure as all work was completed as per previously													
NMOCD/NM	ISLO appr	oved work p	lan			15 20. 200	T requests closu	ire as an	WOIR WA	scompleteu	as per	previously	
				is true and compl	ete to t	he best of my	knowledge and u	nderstand	that purs	uant to NM(OCD ru	les and	
				d/or file certain re									
public health	or the envir	onment. The	acceptanc	e of a C-141 repo	rt by the	e NMOCD m	arked as "Final Re	eport" do	es not reli	eve the oper	ator of	liability	
should their o	perations h	ave failed to a	adequately	investigate and re	emediat	e contaminati	on that pose a thre	eat to gro	und water	, surface wa	ter, hun	nan health	
				tance of a C-141	eport d	oes not reliev	e the operator of r	esponsib	ility for co	ompliance w	ith any	other	
federal, state,	or local lav	vs and/or regu	lations.										
(1	•	~				OIL CONS	SERVA	ATION	DIVISIO	N		
0.	lub	Cai	4-0										
Signature:	une	er ong	then										
Printed Name	. Amber G	riffin			Approved by Environmental Specialist:								
1 milleu Ivaille	. Amoer G	1111111											
Title: Rep Sa	fety & Env	ironmental II				Approval Dat	e:	E	piration I	Date:			
	CC 13111					-pp.0 fui Dai			-Priation I				
E-mail Addre	ss: amber	griffin@eogre	esources.c	om		Conditions of Approval:				Attached			
							IRP- 4342			Attached			
Date: April 3	, 2017		P	none: 575-748-41	2								

* Attach Additional Sheets If Necessary