

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating, LLC (OGRID# 229137)	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No.: 432-683-7443
Facility Name: ALBATROSS STATE COM #002H	Facility Type: Wellhead

Surface Owner: State	Mineral Owner: State	API No.: 30-25-41544
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	30	18S	35E	190	North	1989	East	Lea

Latitude: 32.725502 Longitude: -103.4947205 NAD83

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 10 bbls Oil	Volume Recovered: 7 bbls Oil
Source of Release: Wellhead	Date and Hour of Occurrence: 1-23-2018	Date and Hour of Discovery: 1-23-2018 9:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	APPROVED <i>By Olivia Yu at 7:31 am, Nov 06, 2018</i>
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* This release was caused by a valve that was in the wrong position. The valve was placed into the correct position.

Describe Area Affected and Cleanup Action Taken.*

This release remained on the well pad location. A vacuum truck was dispatched to recover all freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

Remediation activities were conducted in accordance with applicable NMOCD Guidelines. Impacted soil affected above the NMOCD Recommended Remediation Action Levels was excavated and transported to an NMOCD-approved disposal facility. Laboratory analytical results from excavation confirmation samples indicated Benzene, BTEX, TPH and chloride concentrations were below the NMOCD RRAL. Upon collecting the required excavation samples, the excavated area was backfilled with locally sourced, non-impacted "like" material. Please reference the Remediation Summary and Closure Report, dated September 13, 2018, for additional details regarding remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>		OIL CONSERVATION DIVISION	
Printed Name: Rebecca Haskell		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior HSE Coordinator		Approval Date: 11/6/2018	Expiration Date: xx/xx/xxxx
E-mail Address RHaskell@concho.com		Conditions of Approval:	
Date: 10/18/2018 Phone: 432-818-2372		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

1RP-4944