

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	NCH1836234042
District RP	1RP-5294
Facility ID	
Application ID	pCH1836239982

## Release Notification

### Responsible Party

Responsible Party	V-F Petroleum Inc	OGRID	24019
Contact Name	Eric Sprinkle	Contact Telephone	432-683-3344
Contact email	Eric@VF-Petroleum.com	Incident # (assigned to)	NCH1836234042 STATE AF #2 @ 30-025-20979
Contact mailing address	Eaton Center Tower 11 500 W Texas, Suite 350 P.O. Box 1889 Midland, Tx. 79702		

### Location of Release Source

Latitude 32.75596 Longitude -103.47806  
(NAD 83 in decimal degrees to 5 decimal places)

Site Name	State AF #2	Site Type	Oil & Gas Pumping Well
Date Release Discovered	11-25-18	API# (if applicable)	30-025-20979

Unit Letter	Section	Township	Range	County
0	8	18S	35E	Lea, N.M.

Surface Owner: ☒ State ☐ Federal ☐ Tribal ☐ Private (Name: Bill Lee)

### State Minerals

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water > 10,000 mg/l?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No ?
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release Illegal Dump, By Unknown Operator.

Form C-141

Page 2

State of New Mexico  
Oil Conservation Division

Incident ID	NCH1836234042
District RP	1RP-5294
Facility ID	
Application ID	pCH1836239982

Was this a major release as defined by 19.15.29.7(A) NMAC?  <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?  <i>Illegal Dump</i>
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?	

**Initial Response***The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

<input type="checkbox"/> The source of the release has been stopped.	
<input type="checkbox"/> The impacted area has been secured to protect human health and the environment.	
<input type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.	
<input type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:  <i>Illegal Dump</i>	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <i>Chris Mabrey</i>	Title: <i>Field Foreman IC</i>
Signature: <i>[Signature]</i>	Date: <i>11-30-18</i>
email: <i>CNM36@live.com</i>	Telephone: <i>432-664-2451</i> <i>" " 5316</i>
<b>OCD Only</b> <b>RECEIVED</b> Received by <i>CHernandez</i> at 11:54 am, Dec 28, 2018	