

**From:** [Hernandez, Christina, EMNRD](#)  
**To:** ["Joel Lowry"; Clyde Wilhoit](#)  
**Subject:** RE: 1RP-5167 - Lea South Battery - Site Assessment Report and Proposed Remediation Plan  
**Date:** Wednesday, January 16, 2019 3:03:00 PM  
**Attachments:** [1RP-5167 Signed C-141 Pages3-5.pdf](#)  
[1RP-5167 - Lea South Battery - Site Assessment Report and Proposed Remediation Plan.pdf](#)  
[image002.png](#)

---

Mr. Lowry:

Notes

The GPS coordinates have been modified. The well number you submitted on the C-141 pages 3-5 and remediation work plan, 30-025-02709, corresponds to a different operator. A facility identification number has been issued for your convenience.

The delineation submitted for **1RP-5167** is incomplete at SP #1, SP #2, SP #3. Per regulation 19.15.29.11A.(5)(d) NMAC, a minimum of two soil samples from each borehole/sample location must be submitted for laboratory analysis. In the interest of resolving 1RP-5167, the remediation and sampling plan submitted is approved. The following is requested:

1. Confirmation sampling must include the sidewall at the border between the excavated area for SP #5/SP #4 and SP #3.
2. Dated photo documentation of the remedial activities and excavated floor.
3. Scaled map with the confirmation sample locations in relation to the delineation sample points.

Thanks,  
Christina Hernandez  
EMNRD-OCD  
Environmental Specialist  
1625 N. French Drive  
Hobbs, NM 88240  
575-393-6161 x111  
[Christina.Hernandez@state.nm.us](mailto:Christina.Hernandez@state.nm.us)

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

---

**From:** Joel Lowry <[joel@lowryenvironmental.com](mailto:joel@lowryenvironmental.com)>  
**Sent:** Friday, December 7, 2018 7:53 AM  
**To:** Hernandez, Christina, EMNRD <[Christina.Hernandez@state.nm.us](mailto:Christina.Hernandez@state.nm.us)>; Clyde Wilhoit

<cwilhoit@legacyreserves.com>

**Subject:** [EXT] 1RP-5167 - Lea South Battery - Site Assessment Report and Proposed Remediation Plan

Ms. Hernandez,

Please find attached the Site Assessment Report and Proposed Remediation Plan that has been prepared for Legacy's Lea South Battery. The Site is located in UL "I", Section 24, Township 20 South, Range 34 East in Lea County, New Mexico. Upon your review and approval, Legacy is prepared to continue remediation activities as outlined within the attached. If you have any questions or need any additional information, please feel free to contact myself or Clyde Wilhoit by phone or email. Thanks.

Respectfully,

**Joel Lowry**

Environmental Professional



*The content of this email may be confidential and/or privileged. If you are not the intended recipient, or an authorized representative of the intended recipient, please notify Lowry Environmental and delete this email from your system at your earliest convenience. Dissemination or copying of this email, its content or its attachments is prohibited.*