

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	3002520781
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B-2317
7. Lease Name or Unit Agreement Name	VACUUM GLORIETA WEST UNIT
8. Well No.	83
9. Pool Name or Wildcat	VACUUM GLORIETA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	CHEVRON USA INC
3. Address of Operator	15 SMITH ROAD, MIDLAND, TX 79705
4. Well Location	Unit Letter <u>J</u> : <u>1980</u> Feet From The <u>SOUTH</u> Line and <u>1785</u> Feet From The <u>EAST</u> Line Section <u>35</u> Township <u>17S</u> Range <u>34E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4013'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ HORIZONTAL COMPLETION

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-26-04: MIRU. TIH W/PKR & SET @ 4954. REL PKR. 3-29-04: ISOLATE HOLES IN CSG FR 4268-4702. TIH TO 4720.
3-30-04: SPOT 100 SX CMT ACR BAD SPOT IN CSG 4215-4720. DISPL W/22.5 BBLS FW. 3-31-04: TAG CMT @ 4136. DRILL CMT STRINGERS TO 4472'. 4-01-04: DRILL CMT STRINGERS TO 4560. FELL THRU. WENT DN TO 4690. CHART & TEST TO 225# FOR 30 MINS. LOST 25#. THREE TIMES. CHART & TEST TO 340#. LOST 40# TWICE. TIH TO 1253. 4-02-04: TIH TO 4688.
4-05-04: SPOT 100 SX CMT ACR PERFS 4250-4688. DISPL W/24 BBLS FW. SQZD 1.7 BBLS CMT @ 1085#.
4-06-04: TIH & TAG CMT @ 4310. DRILL 395' OF CMT TO 4705. FELL THRU. WENT TO 4751. CHART TO 340# FOR 35 MINS. (CHART ATTACHED)
4-07-04: TAG @ 4850. WSH DN TO RBP @ 4996. REL PLUG. TIH TO 1570'. 4-08-04: PU PKR - COULD NOT SET.
4-09-04: TIH W/PKR & SET @ 5180. 4-16-04: MIRU COIL TBG UNIT. JET CLEAN 7736-7874.
4-19-04: RU SWAB. 16 RUNS. 4-20-04: REL PKR. PU RBP & PKR TOL 1270.
4-21-04: SET RBP @ 5000. PULL PKR TO 4988. SET PKR @ 4675. ISOLATE LEAKS FR 4301-4675. REL PKR. TIH TO 4700 & DUMP 2 SX SAND ON RBP. 4-23-04: DISPL W/180 BBLS FW. SPOT 100 SX CMT ACR OLD SAN ANDRES PERFS 4671-4300.
4-26-04: TAG CMT @ 4219. DRILL 4219-4405, 4720. WASH SAND OFF RBP. REL RBP & PULL UP TO 4380. 4-28-04: TIH W/MOTOR, SEAL, GAS SEP, PMP & TBG. 4-29-04: RIG DOWN. CLEAN LOCATION.
5-02-04: ON 24 HR OPT. PUMPING 184 OIL, 208 GAS, & 248 WATER.
5-03-04: MIRU KEY. TIH W/2 7/8" TBG TO 1875. 5-04-04: LATCH ONTO WHIPSTOCK @ 5743. JAR LOOSE. TIH TO 5743.
5-05-04: LOWER BIT TO TAG CIBP @ 5760. DRILL ON CIBP. TURN LOOSE & PUSH DN TO 5860.
5-06-04: TIH W/MOTOR, SEAL, PMP, TBG SUB, & TBG. RIG DOWN.

BHL: L 1979' fsl, 526' fsl

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Paul F. Kautz TITLE Regulatory Specialist

DATE 5/24/2004

TYPE OR PRINT NAME PAUL F. KAUTZ

Telephone No. 915-687-7375

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

PETROLEUM ENGINEER

JUN 02 2004
DATE

