

Deviation survey taken on CHESAPEAKE OPERATING
in Lea County, New Mexico

BURRUS 26-2 E-26-125-38e
2228/N 9524/W
30-025-36715

Depth	Deviation
225	0.50
417	0.75
685	1.75
798	2.50
890	3.25
922	1.75
1168	0.75
1268	0.75
1350	0.75
1443	0.75
1537	0.75
1760	1.75
1883	1.50
2004	1.25
2128	1.00
2341	1.50
2743	1.50
3053	1.50
3392	1.00
4317	1.00
4520	0.75
4776	1.25
5024	1.25
5363	1.75
5732	1.75
6226	2.50
6507	2.25
6756	1.75
7070	2.25
7193	2.25
7445	2.75
7600	2.75
7881	2.75
8268	3.00
8565	2.75
8968	2.75
9406	2.75
9800	2.75



Before me, the undersigned authority, on this day personally appeared G. M. HALL, known to me to be the person whose name is subscribed hereto, who, after being duly sworn, on oath states that he is the drilling contractor of the well identified in this instrument and that such well was not intentionally deviated from the vertical whatsoever.

SWORN AND SUBSCRIBED TO before me this the

G. M. Hall
13th day of July 2004

Donna J. Minnick

