

NUMBER OF COPIES RECEIVED

DISTRIBUTION

SANTA FE

FILE

U.S.G.S.

LAND OFFICE

TRANSPORTER

OIL  
GAS

PRODUCTION OFFICE

OPERATOR

## NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103  
(Rev 3-55)

## MISCELLANEOUS REPORTS ON WELLS C. C.

(Submit to appropriate District Office as per Commission Rule 184)

MAY 7 12 54 PM '64

Name of Company <b>Marathon Oil Company</b>				Address <b>Box 220 - Hobbs, New Mexico</b>			
Lease <b>Milton Basham "A"</b>		Well No. <b>1</b>	Unit Letter <b>D</b>	Section <b>19</b>	Township <b>8 S</b>	Range <b>37 E</b>	
Date Work Performed <b>4-15-64</b>		Pool <b>San Andres</b>			County <b>Roosevelt</b>		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
- ☐ Plugging
 ☒ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Total depth 9567'; PBTD 5000'. "BJ" Service attempted to sand frac thru perfs in 7" csg @ 4920-24' in San Andres Section w/10,000 gal lease oil w/ 1/20th pound of Adomite per gallon & 15,000 pounds sand. Pumped 5200 pounds sand into formation & well sanding out. Cleaned out sand to 5000', PBTD. Placed well on pump & now recovering load oil.

Witnessed by <b>R. R. Patterson</b>	Position <b>Asst. Foreman</b>	Company <b>Marathon Oil Company</b>
----------------------------------------	----------------------------------	----------------------------------------

## FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

## ORIGINAL WELL DATA


D F Elev. <b>4065'</b>	T D <b>9567'</b>	PBTD <b>5000'</b>	Producing Interval <b>4920 - 24'</b>	Completion Date <b>6-3-60</b>
Tubing Diameter <b>2-3/8"</b>	Tubing Depth <b>4921'</b>	Oil String Diameter <b>7"</b>	Oil String Depth <b>9536'</b>	
Perforated Interval(s) <b>4920 - 24 w/4 JSPF</b>				
Open Hole Interval		Producing Formation(s) <b>San Andres</b>		

## RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover	<b>3/26/64</b>	<b>5.56</b>	<b>too small to meter</b>	<b>31</b>		
After Workover	<b>5/1/64</b>	<b>5.0</b>	<b>"</b>	<b>30</b>		

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by 	Name <b>Albert M. Schler, Jr.</b>
Title <b>Engineer District 1</b>	Position <b>Asst. Supt.</b>
Date <b>MAY 10 1964</b>	Company <b>Marathon Oil Company</b>