

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Water Injection Well</b>	7. Unit Agreement Name <b>West Dollarhide Queen Sand Unit</b>
2. Name of Operator <b>Skelly Oil Company</b>	8. Farm or Lease Name <b>West Dollarhide Queen Sand Unit</b>
3. Address of Operator <b>P. O. Box 1351, Midland, Texas 79701</b>	9. Well No. <b>3</b>
4. Location of Well UNIT LETTER <b>M</b> <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>990</b> FEET FROM THE <b>West</b> LINE, SECTION <b>19</b> TOWNSHIP <b>24S</b> RANGE <b>38E</b> NMPM.	10. Field and Pool, or Wildcat <b>Dollarhide Queen</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3130' DF</b>	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- Moved in pulling unit 5-10-73. Pulled tubing and packer.
- Set 5-1/2" bridge plug at 3650'.
- Circulated with 10# mud.
- Spotted 15 sack cement plug 3524-3650'.
- Spotted 100 sack cement plug 909-1791'.
- Spotted 10 sack cement plug, surface - 21'.
- Set dry hole marker.

No casing was pulled. The 8-5/8" OD 24# casing set at 1224', and 5-1/2" OD 14# casing set at 3696' were left in the hole. All intervals not cemented were filled with 10# mud.

Well plugged and abandoned 5-10-73.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

(Signed) J. R. Avent J. R. Avent TITLE Dist. Admin. Coordinator DATE May 21, 1973

PROVED BY *John A. Remyson* TITLE Geologist DATE JUN 11 1974

CONDITIONS OF APPROVAL, IF ANY: