

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.	30-025-32551
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	LC 063965
7. Lease Name or Unit Agreement Name	Cooper Jal Unit
8. Well Number	419
9. OGRID Number	193003
10. Pool name or Wildcat	JALMAT: Tansill, Yates & 7-Rivers.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

SDG Resources L. P.

3. Address of Operator

P. O. Box 1390
Montrose, CO 81401

4. Well Location

Unit Letter P : 330 feet from the SOUTH line and 550 feet from the EAST line
Section 13 Township 24S Range 36E NMPM LEA County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3,315' GL

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type Depth to Groundwater feet Distance from nearest fresh water well > feet Distance from nearest surface water > feet

Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material Synthetic

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐


OTHER:

OTHER: Changed out bad tubing, rod boxes and pump. ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Objective: Changed out bad tubing, rod boxes and pump.

1. Rigged up Pulling Unit on 06/18/98.
2. Pulled rods and pump.
3. Changed out 79 - 2 7/8" joints of tubing; 33 - 3/4", 43 - 7/8", 40 - 1" rod boxes and pump.
4. RIH with pump and rods.
5. Placed well on production.
6. 06/23/98: Pump 27 oil, 216 water, 7 mcf.



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Domingo Canales TITLE Senior Petroleum Engineer DATE 11/12/04

Type or print name
For State Use Only

E-mail address: Domingo@sdgresources.com Telephone No. 432-550-7580

APPROVED BY: [Signature] TITLE PETROLEUM ENGINEER DATE FEB 16 2005
Conditions of Approval (if any):