Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103
District I	Energy, Minerals and Natural Resources		May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II		WELL A 30-025-3	
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		JIVISION 5 Indica	ate Type of Lease
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410		is Dr. S'	TATE FEE
District IV	Santa Fe, NM 875	0. 0	Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		34177	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Name or Unit Agreement Name
PROPOSALS.)			3 State Number
1. Type of Well: Oil Well Gas Well Other			variio Ci
2. Name of Operator Gruy Petroleum Management Co.		9. OGR 162683	ID Number
3. Address of Operator		1 ' '	l name or Wildcat
PO Box 140904; Irving, TX 75014		Wildcat;	Morrow
4. Well Location 990			
Unit Letter D: 4660 feet from the North line and 660 feet from the West line			
Section 23 Township 17S Range 34E NMPM County Lea			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3410' GR			
Pit or Below-grade Tank Application ☑ or Closure □			
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water			
Pit Liner Thickness: Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING			
TEMPORARILY ABANDON			
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT JOB	
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
of recompletion.			
	ole . Ran 10 jts 13-3/8" 54.5#		
with lead 250 sx Premium Plus + 4% Gel + 2% CC + 0.25% Flocele + 4% Bentonite and tail 200 sx			
Premium Plus + 2% CaCl. Circulated 104 sx to pit. Tested casing to 500psi. WOC 19.25 hours.			
03-01-05 Ran 109 jts 9-5/8" 40# NS-110HC 8rd LT&C New Inspected casing to 4522' in 12-1/4" hole.			
Cemented with lead 1160 sx Interfill C + 1/4# Flocele and tail 200 sx Premium Plus + 2% CaCl. Circulated 5 sx to pit. Tested casing to 1550 psi. WOC 15.25 hours.			
Circulated 3 sx	to pit. Tested casing to 1550 j	osi. WOC 15.25 nours.	
			100 100
			Sagna
			CALCULATED AND AND AND AND AND AND AND AND AND AN
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines X, a general permit or an (attached) alternative OCD-approved plan.			
SIGNATURE Watalin Kunger TITLE Regulatory Analyst DATE March 10, 2005			
	TITLE RE	Suidioi y Tillalyst	DATE_Water 10, 2003
Type or print name Natalie Krue	eger email address:	nkrueger@magnumhunter.	<u>com</u> Telephone No <u>. 972-401-3111</u>
For State Use Only	•	- 4	r <b>f</b> R
APPROVED BY:	TITLE	ENGIN	DATE.
Conditions of Approval (if any):		PETROLEUM ENGIN	MAR 1 4 2005
		<i>a</i>	