

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-01494
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2148
7. Lease Name or Unit Agreement Name Caprock Maljamar Unit
8. Well Number 84
9. OGRID Number 022922
10. Pool name or Wildcat Maljamar Grayburg San Andres

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> WIW	
2. Name of Operator The Wiser Oil Company	
3. Address of Operator P.O. Box 2568 Hobbs, New Mexico 88241	
4. Well Location Unit Letter <u>P</u> : <u>660</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>East</u> line Section <u>20</u> Township <u>17S</u> Range <u>33E</u> NMPM Lea County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4181' GR	
Pit or Below-grade Tank Application <input checked="" type="checkbox"/> or Closure <input type="checkbox"/>	
Pit type <u>Workover</u> Depth to Groundwater <u>147'</u> Distance from nearest fresh water well <u>1000'</u> + Distance from nearest surface water <u>1000'</u> +	
Pit Liner Thickness: <u>12</u> mil Below-Grade Tank: Volume <u>100</u> bbls; Construction Material	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: Repair leak ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Wiser Oil request approval to repair above well by procedure listed below:
Perforations: 4234'-4409' Open Hole

1. MIRU PU. ND WH. NU BOP. POH w/pkr.
2. Test casing for possible leaks.
3. Repair all leaks.
4. Circulate pkr. fluid.
5. Test csg. to 500 psi for 30 min. w/a pressure drop of not greater than 10%.
6. Place well back on injection.
7. RDMO well service unit.
8. Clean location.

* Notify NMOCD 24 hrs. prior to testing pkr.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Mary Jo Turner TITLE Production Analyst DATE March 24, 2005

Type or print name Mary Jo Turner E-mail address: mjturner@forestoil.com Telephone No. 505 392-9797

For State Use Only

APPROVED BY: Harry W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE MAR 28 2005
Conditions of Approval (if any):

