

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

May 27, 2004

WELL API NO.

30-025-22194

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
DEEP SPARKLING MUDDLER
STATE 15

8. Well Number 1

9. OGRID Number 05898

10. Pool name or Wildcat
WILDCAT, MISSISSIPPI

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

DAVID H. ARRINGTON OIL & GAS, IN

3. Address of Operator

P. O. BOX 2071
MIDLAND, TEXAS 79702

4. Well Location

Unit Letter O : 660 feet from the S line and 1980 feet from the E line
Section 15 Township 17S Range 36E NMPNM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
2841.8' GROUND

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water

Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☒

OTHER: ☐


13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

08-16-2004

SPOT 290 SKS. PLUG FROM 3,220' - 2,800'.

09-01-2004

RUN 8-5/8" CSG., 122 JTS. 32#/FT., 8RD, STC CSG. SHOE @ 5,258', FLOAT COLLAR @ 5,212'. CEMENT W/1685 SKS. PREM PLUS, TAIL W/200 SKS. PREM PLUG. BUMPED PLUG. WOC 4 HRS. ND BOP. SET SLIPS, TEST, & NU BOP.



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Nancy Getz

TITLE PROD. ANALYST

DATE 03/16/2004

Type or print name NANCY GETZ

E-mail address: nancyg@arringtonoil.com

Telephone No. (432)682-6685

For State Use Only

APPROVED BY: [Signature]
Conditions of Approval (if any):

TITLE

PETROLEUM ENGINEER

DATE MAR 29 2005