



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

Susana Martinez
Governor

John H. Bemis
Cabinet Secretary

Jami Bailey
Division Director
Oil Conservation Division

Response Required – Deadline Enclosed

State Inspection Program

"Preserving the Integrity of Our Environment"

15-Jun-11

EOR OPERATING COMPANY

One Riverway SUITE 610
Houston TX 77056

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

MILNESAND UNIT No.124				K-7-8S-35E	30-041-00031-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/08/2011	Routine/Periodic	Maxey Brown	Yes	No	9/11/2011	iMGB1115939330
Violations						
Absent Well Identification Signs (Rule 103)						
Comments on Inspection:		NO WELL SIGN RULE 19,15,16.8. NEED TO INSTALL WELL SIGN VALVE ON TBG HAS BEEN REPAIRED. WELL IS T/A'D, BUT EXPIRED THIS IS 1ST LETTER OF NON-COMPLIANCE. MGB				

MILNESAND UNIT No.036				N-18-8S-35E	30-041-00087-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/08/2011	Routine/Periodic	Maxey Brown	Yes	No	9/11/2011	iMGB1115946472
Violations						
Absent Well Identification Signs (Rule 103)						
Comments on Inspection:		NO Well Sign (Rule 19 15 16 8) NEED TO INSTALL WELL SIGN. THIS IS 1ST LETTER OF NON-COMPLIANCE MGB				

Oil Conservation Division : 1625 N. French Drive : Hobbs, New Mexico 88240

Phone 575-393-6161 * Fax 575-393-0720

<http://www.emnrd.state.nm.us>

MILNESAND UNIT No.186

G-18-8S-35E

30-041-10194-00-00

Inspection Date	Type Inspection	Inspector	Violation?	⁴ Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/08/2011	Routine/Periodic	Maxey Brown	Yes	No	9/11/2011	iMGB1115942827


Violations

Absent Well Identification Signs (Rule 103)

Comments on Inspection: WELL SIGN, RULE 19 15 16 8 NEED TO REPLACE WELL SIGN. UNABLE TO READ. PUMPING UNIT IS RUNNING SURPLUS P. UNIT ON WESTSIDE OF LOCATION. THIS IS 1ST LETTER OF NON-COMPLIANCE. MGB.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,




COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data
⁴Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER	015H14150977	US POSTAGE
	\$0.44	
	06/16/11	
	Mailed From 88240	

1 EOR OPERATING COMPANY
ONE RIVERWAY SUITE 610
HOUSTON TX 77056